Service Repair Sheet SRS67606

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Alan McInnes

West Cumberland Hospital

Medical Engineering

01946 523109

01228 523444

00000970

alan.mcinnes@ncuh.nhs.uk

06/Oct/2020

Robert Connor

Viamed

Warranty

Notes 01/Oct/2020 Zoey Teal

· 01/Oct/2020 Zoey Teal

Sending back a pair of R-22Vi sensors. Failed calibration checks.

Serial numbers V103411/V103412

06/Oct/2020 Robert Connor

R22Vi pair V103411/12

Ready For quote

Repair Complete Signed

<u>ean</u> 12-10-2020

| SRN | Equipment | Stock Ref | Serial Number | Warranty |
|----------|---------------|-----------|-----------------|----------|
| SRN33141 | Oxygen Sensor | 0110072 | V103411/V103412 | Yes |

0140011 × 1 FCC S/N, 5RS, 5RN



Alan Mo Medical Engineering Depar West Cumberland Ho White Cui

Tel No. 01946 52

CA2

Date: 02/10 /:

Dear Sir/Madam

Please find enclosed paired O2 cells (s/n V103411 and V103412) returned because they failed calibration checks. Please can you supply replacements under warranty.

Alan McInnes