



SRS67494 oxygen sensor returns status



Steve Nixon <steve.nixon@vandagraphst.com>
to Jim, Shaun, Duncan, Sarah

Good morning

The status of the oxygen sensor returns is as follows:

SRS67494

167 sensors returned to VST 2nd June 2020

6 sensors out of warranty and returned to JFD

152 sensors were reworked and returned back to JFD

We will generate a FOC order to cover the following 9 sensors:

2 sensors retained by VST and replaced as good-will

SN	SRS	SRN	
1359045	SRS67494	32781	To be replaced as good-will gesture
1440970	SRS67494	32782	To be replaced as good-will gesture

7 sensors, to be replaced with new sensors

SN	SRS	SRN	
101171	SRS67494	32629	To be replaced
101413	SRS67494	32657	To be replaced
101477	SRS67494	32689	To be replaced
101491	SRS67494	32693	To be replaced
101496	SRS67494	32696	To be replaced
101500	SRS67494	32697	To be replaced
101564	SRS67494	32750	To be replaced

