

University Hospitals of Morecambe Bay NHS Foundation Trust Medical Engineering Department



FIXED PRICE REPAIR

Job Reference 181387 Date: 04/12/2020

Equipment Details

Asset Number 212201

Serial Number E410 6401458

Description VIAMED RESUS CABINET RESUSCITAIRE - Tom T

Department FGH SOUTH LAKES BIRTH CENTRE-DELIVERY
Fault / Additional Info Resus will not read under 50 mmHg/Sticky dial

Action Required

Please find enclosed the above faulty unit requiring repair.

This has been discussed with your company previously and a fixed price repair has been agreed. The purchase order details are below.

Purchase Order Number: UHMB1126420

Purchase Order Value: 272.40

PLEASE SEND ANY CORRESPONDENCE TO THE EMAIL ADDRESSES BELOW

Michael.Salmon@mbht.nhs.uk

and cc medical.engineering@mbht.nhs.uk

Declaration

This equipment has been decontaminated in accordance with the Trusts Equipment

Decontamination Policy.

Signature ___

Return Address

Michael Salmon

Medical Engineering

Furness General Hospital

Dalton Lane

Barrow

LA14 4LF

Tel: 01229 491116