

Service Repair Sheet SRS67774

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Anita Birkett

Lincoln County Hospital

NICU

Resp Tech

01522 57 31 41/ 01522 573663

0152 251 2512

00002610

Anita.Birkett@ulh.nhs.uk

29/Mar/2021

Catherine Spence

Viamed

Quote

new £90.

Asked by customer
to dispose of
sensors 29.3.21

Notes 22/Mar/2021 Steve Hardaker

22/Mar/2021 Steve Hardaker

22/Mar/2021 Steve Hardaker

Returning 1x 0110043 matched pair of R-43V, s/n 106910 & s/n 106759 sold as a pair 28/7/20, failed after 5 months in service.

Customer reports low output, both reading around 20mV in air.

29/Mar/2021 Catherine Spence

received in S/N V1069910 and V106759 ran out of warranty 28/01/2021

Ready For quote

Repair Complete Signed

Caneon 31.3.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33500	Oxygen Sensor	0110043	V106759/V106910	N

0140016 x 1 @ £0.

S/N, SRS, S&N.

Edit Wording: faulty, not under warranty.
Disposed of as requested by customer.



hcc 349009

Endosed are our faulty
sensors serial numbers
V106759 and V106910
which have failed after
only 5 months use.

Please can you supply
some replacement
sensors Thank you.

Yours sincerely

Anita Birkett

United Lincolnshire Hospitals 
NHS Trust

Lincoln County Hosp
Greetwell Road
Lincoln
LN2 5QY

Returns re
SRS6777

Mrs Anita Birkett
Specialist Clinical Engineering Technician
Clinical Engineering Dept
Direct Dial: +44 (0) 1522 573663
Email: Anita.Birkett@ulh.nhs.uk