

Quality Assurance System			
Temperature Probes			
Manufacturer	Betatherm		
Part Number	37000 series	Version	08 June 1999

1. Visual Check of cable for:
  - Nodules
  - Cuts
  - Stains
2. Visual Check Thermistor end for:
  - Nodules
  - Burrs
  - Discolouring
  - Bare wires
3. Visual Check Connector for
  - Clean entrance of cable
  - Nos loose cable strands inside connector
  - Connector is clean
4. Check electrical resistance should be nominally 2K5 @ room temperature