

Memorandum

To: John Lamb

CC:

From: Peter Spavin

Date: 14/05/99

Re: VN202

VARIATION IN SPECIFICATION - 14/05/99.

Due to variations in the quality of the sensor cable for this unit causing parasitic oscillation in the amplifier circuit the screen connection to the ground-plane of the P.c.b. should be omitted. This modification will in no way compromise normal operation or invalidate the unit's CE marking.

J.P. Spavin