

VN202 Parts

Status	Loc	Part Number	Description	Supplier	qty to order to make 100
A	A1	714-562	Acrylic Conformal Coating	RS	2
A	A3	504-530	Supadrive pan head M4 x 6.4	RS	4
A	A4		Link wire 1 cm		
A	A5		Unibond General Si sealant	BQ	
A	B1	BT00114	PP3 Alkaline 9v battery	CPC	
A	C1	126-512	10nF Capacitor	RS	100
A	C2	116-802	Electro Cap 33UF 16V	RS	100
	C3	125-749	Capacitor	RS	100
A	CL1		Coiled cable 2 core yellow	MWC	50
A	D1	1N4148	Diodes 1N4148	FAR	1
A	E1	34501000	Integral battery case style 4 type2	BOP	100
A	E2		Case logo Scrn Prnt	GF	100
A	E3	INENG	Instruction Case Insert	JSL	100
A	E4	R23	Yellow enclosure LARGE		100
A	F1	VN10KM	VN10KM Transistor	FAR	100
	FC1	FC1	R-17 Sensor	TED	100
A	G1	543-197	Grommet 4.0mm	RS	1
A	G2	268-495	Tie wrap small	FAR	1
A	IC1	DPM400	Ultra Low power LCD DPM400	LAS	100
A	IC2	TLO71CP	TL071CP OP AMP	FAR	100
A	IC3	384-630	HEF4013BP	FAR	100
A	L1	VNL3	Front Label VN202 Lge	REN	100
A	L2	VNL2	Front Label VN202 Oxygen Analyser.	REN	100
A	L3	VNL4	Top Label Logo	REN	100
A	L4	VNL1	Rear label Instruction	REN	100
A	L5	VNL5	Serial Number label	REN	100
A	M1		Instruction manual	JSL	100
	M1	152-659	Shielding tape, copper	FAR	1
	M2	568-483	RFI shielding spray	RS	2
	M3	501-311	Masking tape	FAR	2
	M4		Solder		1
A	P1	348-843	10MM M/T CERMET TRIM 1K	FAR	100
A	PC1	Divox-1-94	Printed Circuit Board only	PM	100
A	R1	514-342	0.125W Metal film 22 Kohmn	FAR	100
A	R10	333-153	RES HYSTAB 0.25W/6M8	FAR	100
A	R11	514-263	0.125W Metal Film 10Kohm	FAR	100
A	R2	514-184	0.125W METAL FILM 4K7	FAR	100
A	R3	514-240	0.125W METAL FILM 8K2	FAR	100
A	R4	514-184	0.125W METAL FILM 4K7	FAR	100
A	R5	514-275	0.125W Metal film 11 Kohmn	FAR	100
A	R6	514-263	0.125W Metal film 10Kohmn	FAR	100
	R6	514-263	0.125W Metal film 10Kohm	FAR	100
A	R8	514-263	0.125W Metal film 10Kohmn	FAR	100
A	R9	514-263	0.125W Metal film 10Kohmn	FAR	100
A	S1	150-245	Push switch waterproof (Yellow)	FAR	20
A	S2	148-921	Push switch waterproof kit	FAR	20
A	SK1	179-888	28 way IC socket	FAR	6
A	SK2	489-021	Twin Min PP3 battery connector	RS	100
A	T1		Labour		
A	VR1	350-655	1W with Knob 10kohms	FAR	100
	W2	526-366	M4 Fibre washer	RS	100
A	WR2	354-515	Ribbon cable 10way	FAR	1