



Warning No company id linked:

Enter CID Number

Link Company ID

SRS67867

[Print Barcodes](#)

[Print A4 Sheet](#)

[Split Items into Different SRS Numbers](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care

Add Items to Supplier Returns Box

- ☐ Return for Credit / Return to Stock
 Unopened - will apply to all items on srs
☐ Clear From System - Force from
 System. - will apply to all items on srs

Add notes to SRS

Service Repair Sheet 67867										Notes	
Company / Hospital	Kevin Woolgar									14/Jun/2021 Ryan Swaine	
Contact Name	Kevin Woolgar									14/Jun/2021 Ryan Swaine	
Department										14/Jun/2021 Ryan Swaine	
Position											
Company Phone	07831 506959									VN202 MK1 - Won t turn on. Repaired 07/2019, not used since.	
Direct Phone	07831 506959									21/Jun/2021 Robert Connor	
Opera Account	CID17777									1 x VN202 s/n VN2373, with yellow carry case and battery	
Email	kevin.woolgar@btinternet.com										
Order Number											
Viamed ORD Number											
Date Received Into building	21 Jun 2021										
Type	Quote Before Repair										
Issues?											

Items for Repair										
SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN33942	Oxygen Analyser VN202			VN 2373	VN202	No	No	Unfinished		00:00

Currently Viewing ITEM SRN33942 Oxygen Analyser VN202 VN 2373 VN202

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	23/Jun/2021 Michael Green The VN202 Oxygen analyser has been tested. The unit	Non added Yet

		does not power up. 23/Jun/2021 Michael Green A fault has been found in the battery lead. The previous repair was a trim pot adjustment. The two faults are unrelated. 23/Jun/2021 Michael Green 7930007 - Battery lead 1 hour	
--	--	--	--

SELECT * FROM Serialnumbers where (1=0 OR Invoicenumber='WSSRN33942')

.