

## Service Repair Sheet 67877

Contact Name	Francis Loch
Company/ Hospital Name	Forth Valley Royal Hospital
Department	Medical Physics
Position	Specialist Clinical Technologist
Direct Phone	01324 566 956
Opera Account	00004880
Email	francis.loch@nhs.scot
Date Received	30/Jun/2021
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33966	0110705	100059	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110705    Oxygen sensor MLF-19

Sensor was wrongly labelled, replaced under warranty with S/N 100066

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33967	0110705	100060	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110705    Oxygen sensor MLF-19

Sensor was wrongly labelled, replaced under warranty with S/N 100067

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33968	0110705	100061	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110705    Oxygen sensor MLF-19

Sensor was wrongly labelled, replaced under warranty with S/N 100072