



Leave Flow diverter and move through fresh air



Calibrate Analyser to 20.9%



Turn on cylinder gently and feel gas flow



With an "O" ring type cylinder mate the dome to the O ring



With A DIN outlet gently push the dome into the DIN thread

When the reading on the analyser stops rising turn off the cylinder. The reading may fall slightly then stop as the pressure reduces. This is the reading of Oxygen in the cylinder