



Risk Analysis

This product has been in use in its present form since 1984

The main risks involved in manufacture are:-

Sharp edges,,

Wrong sizes,

The main risks involved in use are:

The Light shield must fit over the head so that Phototherapy light does not reach the eyes

Possible build up of CO₂ over time. when the full headbox style is used.