

Risk Analysis

This product has been in use in its present form since 1984

The main risks involved in manufacture are:-Sharp edges,,
Wrong sizes,
Protruding screws on the hinges,
Loose screws on the hinges,

The main risks involved in use are:

The lid must fit over the cot and be fitted correctly so that the lid cannot fall off or into the cot.

Possible build up of CO2 over time. Reduced by using the handles as ventillation slots.

Humidity. Users advised to use louvre versions.