

Residual Risk Resuscitation cabinet - CE FILE

Residual Risk Analysis Report.

Rotating Acrylic Bed

The centre of the rotating bed is a bolt which is a source of dirt collection.

When the bed is cleaned this bolt should also be cleaned and checked that the bed rotates freely.

The mattress is round but apart from its shape should be cleaned and handled as in the general body of the manual on bed care and cleaning

The bed should never be left between these positions either in use or in storage.

Care should be taken to prevent the operators fingers becoming trapped in the mechanism Care should be taken to ensure that the patients limbs do not protrude out of the bed perimeter when the bed is being rotated

The patient dropping off. This should never happen as the patient should never be left unattended

Electrical

If the heater case is removed with the unit switched on Wiring failures if wires become disconnected Element is touched. Component failure

Heat

Patient overheat User over heat

Physical Injury

.head of user coming into contact with the heater

See individual risk reports

WARNINGS

See label section and user manual

J.S.lamb

11/02/11