

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634542/636757 Fax: +44 (0)1535 635582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68007

Company/ Hospital Name

Date Received Booked in By

Xhale

29/Nov/2021 Robert Connor

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34362

0110081 648789

Oxygen Sensor

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689220

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34363

0110081 648805

Oxygen Sensor

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689221

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34364 0110081 661674 Oxygen Sensor

Time: 0 Hour(s)

Time: 0 Hour(s)

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689222

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34365

0110081 661684

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689223

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34366

0110081 681639

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689224



Viamed Limited · 15 Station Road · Cross Hills
Keighley · West Yorkshire · BD20 7DT · United Kingdom
Tel: +44 (0)1535 634542/636757 Fax: +44 (0)1535 635582
Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68007 Company/ Hospital Name Date Received Booked in By

Xhale 29/Nov/2021 Robert Connor

Repair

SRN34367

Ref

S/N

0110081 681647

Equipment Type

Oxygen Sensor

Under Warranty

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689225

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34368

0110081 681653

Oxv

Oxygen Sensor

Time: 0 Hour(s)

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689226