

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634542/636757 Fax: +44 (0)1535 635582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68012

Contact Name

Company/ Hospital Name

Date Received Booked in By

Aris Drogosis

Xhale

15/Dec/2021

Robert Connor

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34391

0110081 684367

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689227

Repair

Ref

S/N

Equipment Type

Under Warranty

0110081 684368 SRN34392

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689228

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34393

0110081 684374

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689229

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34394

0110081 684378

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689230

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34395

0110081 684385

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689231



Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634542/636757 Fax: +44 (0)1535 635582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68012

Contact Name

Company/ Hospital Name

Date Received Booked in By

Aris Drogosis

Xhale

15/Dec/2021 Robert Connor

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34396

0110081 684405

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689232

Repair

Ref

S/N

Equipment Type

Under Warranty

0110081 684408 SRN34397

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689233

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34398

0110081 684420

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689234

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34399

0110081 684422

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689235

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34400

0110081 684429

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110081

Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 689236