

Service Repair Sheet 68023

Contact Name	Justina
Company/ Hospital Name	Bleikers Smokehouse Ltd
General Phone	01423 711411
Opera Account	00012873
Email	qc@bleikers.co.uk
Order Number	11366
Date Received	08/Dec/2021
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Calibrated
SRN34386	7900100	01251	Oxygen Analyser VN202	Time :0 Hour(s)

Parts Replaced	Qty: 1	0110117	Oxygen sensor - Automotive R-17A
----------------	--------	---------	----------------------------------

The VN202 analyser and pump box combination have been tested. The VN202 is working as expected and a calibration certificate has been produced. The pump box is drawing a good gas sample. The R-17AV Oxygen sensor (SN:190019) has been tested. The output in Oxygen was found to be out of specification. The Oxygen sensor has been replaced with R-17A SN:601034.

---