

Service Repair Sheet 68024

Contact Name	Paul Cooper
Company/ Hospital Name	Bavaria Blue for Safari
Direct Phone	07966142380
General Phone	00159431430
Opera Account	BAVARIA
Date Received	08/Dec/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN34383	9710203	0933	Oxygen Analyser TEK-OX	Complete - Repaired
				Time :0 Hour(s)

Parts Replaced

Qty: 1 0110217 Oxygen sensor R-17VAN

The TEK-OX analyser has been repaired. The corroded jack connector has been replaced. The R-17VAN Oxygen sensor has been replaced with SN:105305.

Repair	Ref	S/N	Equipment Type	
SRN34384		18604	Oxygen Analyser	Return Unrepaired
				Time :0 Hour(s)

The NRC O2 analyser is not a viable repair. The unit has a soldered battery and would need a sensor. Repairing the unit would be almost as much as a new one.

Repair	Ref	S/N	Equipment Type	
SRN34385		18656	Oxygen Analyser	Return Unrepaired
				Time :0 Hour(s)

The NRC O2 analyser is not a viable repair. The unit has a soldered battery and would need a sensor. Repairing the unit would be almost as much as a new one.
