

Service Repair Sheet 67989

Company/ Hospital Name

General Phone

Email

Date Received

Booked in By

Robert Edwards

07958783326

lynne.dunne@sky.com

22/Nov/2021

Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN34340	7910100	00722	Oxygen Analyser VN202	Complete - Repaired Time :1 Hour(s)

The VN202 Oxygen analyser has been repaired. The battery lead has been replaced. A new T piece with a one way valve has been supplied.

Repair	Ref	S/N	Equipment Type	
SRN34341	0110217	178696	Oxygen Sensor Vandagraph	No Fault Found Time :0 Hour(s)

The R-17VAN Oxygen sensor has been tested. The sensor is working within specification. No fault was found.
