Design Changes QC 28 **Project:** Reason for Change; & Description of Changes made: Date Microprocessor employed 1995 Obsolete microprocessor replaced with PIC16F8. 1999 PCB revised to version 2.3 to accept new microprocessor PCB revised to version 2.4 after audio produced on some stimulators with no-load. 2000 C1 introduced to prevent above