

~~ASK Steve N. If we  
charge for a  
functional test  
£45. @ 26-1-22.~~

Service Repair Sheet SRS68045

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Dave Lloyd

Company/ Hospital Name

Southport & Formby District General Hospital

Department

EBME Department

Position

Technical Practitioner of Specialist Services

Direct Phone

01704704188

General Phone

01704 547471

Opera Account

00004760

Email

davidlloyd1@nhs.net

Order Number

Date Received

19/Jan/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 14/Jan/2022 Sophie Lines

14/Jan/2022 Sophie Lines

Has an AX300 which emits a tone when switched on, but not in alarm state (eg when sensor is disconnected) - would like to know cost of possible repair before deciding if more cost effective to purchase a new analyser

19/Jan/2022 Robert Connor

1 x AX-300 s/n 231096, with coiled cable.

Ready For quote

Repair Complete Signed

CCNEON 26-1-2022

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34650	Oxygen Analyser	0111230	231096	N

0146004 @ £0  
NO fault found.

SIN, SRS, SRN

UPS x 1 @ £0.

**Southport and  
Ormskirk Hospital**  
NHS Trust

Repairs  
Viamed Ltd  
15 Station Road  
Cross Hills  
BD20 7DT

EBME Department  
Southport & Formby District General Hospital  
Town Lane  
Southport  
Merseyside  
PR8 6PN

17<sup>th</sup> January 2022

RE: AX3001 (serial no 231096). Returns number SRS68045

Please find enclosed AX3001 for repair.

Fault: Sounder emits the correct tone when unit is first switched on, but no tone in an alarm state.

Please contact me if you require further information.

Regards

David Lloyd

Tel: 01704 704188

Email: davidlloyd1@nhs.net