

Service Repair Sheet SRS68045

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Dave Lloyd

Southport & Formby District General Hospital

EBME Department

Technical Practitioner of Specialist Services

01704704188

01704 547471

00004760

davidlloyd1@nhs.net

19/Jan/2022

Robert Connor

Viamed

Quote

Notes 14/Jan/2022 Sophie Lines

14/Jan/2022 Sophie Lines

Has an AX300 which emits a tone when switched on, but not in alarm state (eg when sensor is disconnected) - would like to know cost of possible repair before deciding if more cost effective to purchase a new analyser

19/Jan/2022 Robert Connor

1 x AX-300 s/n 231096, with coiled cable.

26/Jan/2022 Catherine Spence

Spoken to Steve N and we will not charge for this check.

Ready For quote

Repair Complete Signed

31-1-2022

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34650	Oxygen Analyser	0111230	231096	N
SRN34657	Oxygen Monitor Cable	0131202	WORK040611	N

0140004 x 1 @ £0
NO fault found
~~S/N, SRS, SRN~~

0140025 x 1 FOC *
S/N, SRS, SRN

UPS x 1 @ £0

please edit
CVM 135149
as * has been
added eg 31-1

Repairs
Viamed Ltd
15 Station Road
Cross Hills
BD20 7DT

EBME Department
Southport & Formby District General Hospital
Town Lane
Southport
Merseyside
PR8 6PN

17th January 2022

RE: AX3001 (serial no 231096). Returns number SRS68045

Please find enclosed AX3001 for repair.

Fault: Sounder emits the correct tone when unit is first switched on, but no tone in an alarm state.

Please contact me if you require further information.

Regards

David Lloyd

Tel: 01704 704188
Email: davidlloyd1@nhs.net