

Service Repair Sheet 68085

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34578	0110081	689229	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110081    Oxygen sensor    UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis

Replaced with S/N:778649

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34579	0110081	689232	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110081    Oxygen sensor    UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis

Replaced with S/N:778652

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34580	0110081	689237	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110081    Oxygen sensor    UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis

Replaced with S/N:778655

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34581	0110081	689238	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110081    Oxygen sensor    UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis

Replaced with S/N:778656

---

Service Repair Sheet 68085

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34582	0110081	689239	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110081    Oxygen sensor    UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis

Replaced with S/N:778657

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34583	0110081	689242	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110081    Oxygen sensor    UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis

Replaced with S/N:778664

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34584	0110081	689243	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110081    Oxygen sensor    UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis

Replaced with S/N:778665

---