Service Repair Sheet SRS68081

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Paul Vernon

Company/ Hospital Name

Royal Bolton Hospital

Department

**EBME** 

Position

Engineer

Direct Phone

Opera Account

General Phone

01204390620 00000590

Email

Order Number

Date Received

23/Feb/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 18/Feb/2022 Sophie Lines

18/Feb/2022 Sophie Lines

V1000 - on/off button doesn t work - sending for repair - S/N: GA71182664

23/Feb/2022 Robert Connor

Received 1 x V1000 s/n GA71182664, with 4 x AA battery, tamper sticker broken.

Ready For quote

Green 28-2-22

Repair Complete Signed

SRN	Equipment Foetal Simulator	Stock Ref	Serial Number	Warranty
SRN34747		1410000	GA71182664	7

Service Repair Sheet SRS68081

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Paul Vernon

Company/ Hospital Name

Royal Bolton Hospital

Department

**EBME** 

Position

Engineer

Direct Phone

General Phone

01204390620

Opera Account

00000590

Email

Order Number

Date Received

23/Feb/2022

Robert Connor

Booked in By Main Company

Viamed

Type Return

Quote

Notes 18/Feb/2022 Sophie Lines 18/Feb/2022 Sophie Lines

V1000 - on/off button doesn t work - sending for repair - S/N: GA71182664

23/Feb/2022 Robert Connor

Received 1 x V1000 s/n GA71182664, with 4 x AA battery, tamper sticker broken.

Ready For quote

I green 28.2.22

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty	
SRN34747 Foetal Simulator		1410000	GA71182664	2	

1430 14800000 × 1 2 EUS SIN, SRS, SRN.

1430295 × 1 8 £35

SRS, SRN

1430297 ≠ 1 2 €12.90

SRS, SRN

1430309 X 1 2 FOC


SRS, SRN

x 1 0 E10

## REPAIRS DESPATCH FORM

# iFM Bolton

TO:	Repairs/Servicing Viamed Ltd 15 Station Road Cross Hills BD20 7DT	Date: 22 February 2022 Returns Number: SRS68061
Postcode		
ATTN. OF	Service Department	Supplier's Contact Tel No:
Please servic	e/repair the following equipment: Re	pair of V1000 GA71182664
Ancillary Item	s Sent:	
Reported Fau	ılt: On/Off button faulty	
Order Numbe	<u>r</u> : N/A	
Our Reference	e Docket Number: TE143 or 154	903
Decontaminat	tion Status:	
		invasive procedure or been in contact with blood, other een cleaned in preparation for inspection, servicing or
222 70	Medipal disinfectant wi	ninated. The method of decontamination was:  The nature of risk and safety precautions to be adopted
are:-		
Return Addr EBME Depa iFM Bolton Royal Bolton Minerva Rd, Farnworth, Bolton BL4 0JR	rtment	
Tel: 01204 Email: paul.	390620 .vernon@boltonft.nhs.uk	

































home

call-log crm

employee external iso

meetings opera lookup

producti returns

sales

stockboo x

### **Select Currency**

Pounds Euros Usd

### Repair SRS68081 Values in Pounds @ �1: �1.00

SRN34747	Foetal Simulator	1410000			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		1430295	1	<b>\$</b> 35.00	<b>\$</b> 35.00
111-44		1430297	1	<b>\$</b> 12.90	<b>\$</b> 12.90
		1430309	1	<b>♦</b> 15.00	<b>\$</b> 15.00
		1480000	1	<b>4</b> 5.00	<b>4</b> 5.00
				Parts Cost	<b>1</b> 07.90

FOC CG 28-2

#### CHECK PRICES BEFORE SENDING QUOTE

Quote Sent