

Service Repair Sheet SRS68083

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Kamal Pacitti

North Middlesex University Hospital

Clinical Engineering Department

Specialist Clinical Engineer

02088873790

00003070

kamal.pacitti@nhs.net

23/Feb/2022

Robert Connor

Viamed

Quote

Notes 21/Feb/2022 Kate Griffiths

21/Feb/2022 Kate Griffiths

Customer has "an Inspiration Healthcare blender, model 2003I which needs servicing as it has lost its calibration. The serial number is BX1854175." SH and I are unable to find s/n on system, maybe bought from Inspiration.

23/Feb/2022 Robert Connor

Received 1 x blender s/n BX1854175

Ready For quote

CGN00028-2-22

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34748	Blender		BX1854175	2

0380019 x 1 @ £340
S/N, SRS, SRN

0332001 x 1 @ £153.95
SRS, SRN

UPS x 1 @ £10

North Middlesex University Hospital **NHS**

NHS Trust

From: North Middlesex University Hospital

Clinical Engineering

Main Building Floor Level [-1]

Sterling Way, London N18 1QX

Tel: 020 88872582

Contact Name: KAMAL PACITTI

E-mail: Kamal.pacitti@nhs.net

Our Ref (Job Req No) RES032A

To: Repairs Team, SR568083,
Vlamed LTD, 15 Station Road,
Cross Hills, Keighley,
West Yorkshire, BD20 7DT

Date: _____

Expected Del Date: _____

Dear..... Repairs Team

Please find enclosed equipment

Serial No:

Low flow blender
Bx 1854175

Please quote us for the cost of the repair by e-mail, so that we can provide you with an order number.

Our order number is: please email with quotation

Fault description:

Black dial clip had come off, blender
no longer accurate, need servicing.
Thank you

DECONTAMINATION (Please tick one)

- ☒ (A) This equipment is NOT as far as I am aware contaminated by any potentially infected material (eg. Blood/body fluids)
- ☐ (B) The equipment may be contaminated by potentially infected material (eg. Blood/body fluids) and has been decontaminated externally, in accordance with the North Middlesex Hospital trust Policy.
- ☐ (C) The equipment may be contaminated with potentially infected material (eg. Blood/body fluids) but could not be decontaminated.

Contaminated/potentially hazardous equipment must be despatched in a sealed container/bag

TRANSPORT/COURIERS NAME:

TNT

PRINT: _____

SIGN: _____

DATE: _____

Catherine Spence Required Reading 1 Calls 25 Issues 14 Unread 10 ISO Tasks |
 H/W: HL RC SW Future Active Users Search



Select Currency

[Pounds](#) | [Euros](#) | [Usd](#)

Repair SRS68083 Values in Pounds @ £1: £1.00

SRN34748	Blender				
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0380019	1	£340.00	£340.00
		0332001	1	£153.95	£153.95
				Parts Cost	£493.95

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent