

Specifications

Weld Wide Solutions *Ar-Gone Weld Gas Analyzer*

Part number: 7910020



Specifications	
Operational range	0 – 100 % oxygen
Display	4.5 digits LCD, 2 decimal places
Display digit height	12.2 mm
Resolution	0.01 %
mV to % ratio	1:1
Display maximum range	200mV
Low battery indication	Yes
Low battery indication threshold	7.2 V typical (6.3 V minimum, 7.7 V maximum)
Battery (included)	9 V, 550 mAh alkaline manganese
Part number: 9950055	
Operating temperature	0 °C to 50 °C
Storage temperature	-10 °C to 60 °C
Operating relative humidity	80%
Dimensions	145 mm (l) x 80 mm (w) x 37 mm (h)
Weight – without battery and oxygen sensor	124 g
Weight - with battery and oxygen sensor	197 g
Oxygen sensor (included)	WGA-01
Part number: 0010370	
Oxygen sensor output in air	25 mV +/- 2 mV