

Service Repair Sheet 66847

Contact Name

Company/ Hospital Name

**Direct Phone** Date Received Booked in By

Colin Matthews Reading BSAC 07939 066524 10/Dec/2018

Catherine Spence

Repair SRN30822

S/N

7910211 TX2216

**Equipment Type** 

Oxygen Analyser TEK-OX

Complete - Repaired

Time:0 Hour(s)

The TEK-OX Oxygen analyser has been repaired. The main PCB has been reconnected.

Repair

SRN30823

Ref

S/N 0110217 735590 **Equipment Type** 

Oxygen Sensor Vandagraph

No Fault Found

Time: 0 Hour(s)

The R-17VAN Oxygen sensor has been tested. No fault was found.

Repair

SRN30827

Ref

S/N 0110217 101797 **Equipment Type** 

Oxygen Sensor Vandagraph

No Fault Found

Time: 0 Hour(s)

The R-17VAN Oxygen sensor has been tested. No fault was found. ACRUSO TO RETAIN AND CLEDIT

ACCOUNT - RS 11/12/18

Company Registration + 23522105