

Service Repair Sheet 67956
Contact Name Paul Raymaekers
Company/ Hospital Name rEvo
Direct Phone 0032 50454405
Opera Account VST006
Email info@revo-rebreathers.com
Date Received 20/Sep/2021
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN34203	8010006	009134944	Oxygen Sensor VST	Replaced Time :0 Hour(s)

No output - sensor replaced as a good will gesture.

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN34204	8010006	010136221	Oxygen Sensor VST	Replaced Time :0 Hour(s)	

No output - sensor replaced under warranty.

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN34205	8010006	101137492	Oxygen Sensor VST	Replaced Time :0 Hour(s)	

No output - sensor replaced under warranty.

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN34206	8010006	101137827	Oxygen Sensor VST	Replaced Time :0 Hour(s)	

No output - sensor replaced under warranty.

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN34207	8010006	107139059	Oxygen Sensor VST	Replaced Time :0 Hour(s)	

Electrolyte leakage - sensor replaced under warranty.
