

Invoice Correction 5259313079

ORIGINAL

Invoice Correction Date: 04.03.2022

Honeywell Healthcare Solutions GmbH

Alter Holzhafen 18

Purchase Order No: RTS3100841

23966 Wismar

Germany

Bill to: 1797471

Vandagraph Limited
15 Station Road
Cross Hills, West Yorkshire
BD20 7DT
KEIGHLEY
United Kingdom

Sold to: 1797448

Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

Order Information:

Credit Memo Request: 63813860
Sales Office: 2170 DE SPS Wismar
Incoterms: FCA Origin
Payment Terms: Net 30 Days After Invoice Date

Ship to: 1797448

Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

ITEM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
000010	E1001721	13	EA	20.00	-260.00	0%
	Oxygen Sensor OOD103-2V					
	Customer Part Nbr: 8010004					
	credit note for SN:					
	127842 ✓					
	128600 ✓					
	128951 ✓					
	130565 ✓					
	130592 ✓					
	130696 ✓					
	130710 ✓					
	130843 ✓					
	131050 ✓					
	132047 ✓					
	132083 ✓					
	133916 ✓					
	133993 ✓					

Totals

Total Before VAT -260.00 EUR
VAT-Total 0.00 EUR
Total Amount -260.00 EUR

Tax Information

Tax Exempt Reason: Tax free export - Goods

Duns #:

Bank Details: No Payment Due

Account Name:

Account No:

Bank Key:

Swift Code:

IBAN:

Payment method:

Registered No: Schwerin HRB 1838

VAT Reg No: DE137437213

Federal ID #:

Registered Address: Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany

Credit Analyst: Xenia Musat

Sales Rep: Stefan Dreyer

Customer Care Rep: Jessica Wagner +49 3841 360 206

Honeywell Healthcare Solutions GmbH

WEEE Reg.No.: 57798680

Internet: www.envitec.com

Managing Director: Marcus Ostländer

email: info@envitec.com

Delivery exclusive to our General Terms (February 2016). We retain title to our goods and deliveries until all the payment from the sales contract have been received. Your order will be executed exclusively to our terms and conditions. These can be sent by separate request or viewed at www.envitec.com

PRÜFBERICHT – TEST REPORT

ENVITEC
by Honeywell

Sauerstoffsensoren/Oxygen Sensors OOA, OOI, OOD

Kunde/ Customer	Vandagrapu	Retour/ RMA- No.	Kunde/ Customer	RTS 3100441	Envitec	300248593
Artikel/ Article	OOD 103-21	Anzahl/ Quantity	13	Eing. Datum/ Inc. Date	31.01.22	
Bearbeitet/ processed	V. B. M.	Prüfdatum/ Insp. Date	08.02.22	Geprüft/ Inspected	31.01.22	

Nr.	Produkt/ Identification		Messwert/ Test Result			Bewertung/ Evaluation		
	Seriennummer/ Serial no.	Lieferlos/ Manufact. code	Luftwert/ Air signal @ 20,9% O ₂ [mV]	Nullsignal/ Offset @ 0% O ₂ [µV]	Linearität/ Linearity [%]	Bemerkung/ Remark	kein Fehler festgestellt/ no failure found	Fehlercode/ Failure- code
1	127842	11120	10.9	10.1	73			2
2	128600	12120	0					4
3	128851	12120	11.8	14	43		x	
4	130565	02121	0					4
5	130582	02121	13.2	11	73		x	
6	130636	02121	11.4	8	43			2
7	130710	02121	11.6	6	43		x	
8	130843	02121	11.2	8	43		x	
9	131050	02121	10.7	7	43		x	1
10	132047	04121	8.90	4	43		x	
11	132083	04121	11.4	4	43			1
12	133316	10121	5.1	5	43		x	
13	133993	10121	11.8	4	43			
14								
15								
16								
17								
18								
19								
20								

Fehler O2-S001: Luftwert außerhalb Toleranz/ Air signal out of tolerance
 Fehler O2-S003: Offset außerhalb Toleranz/ Offset out of tolerance
 Fehler O2-S005: Gehäuse defekt/ Housing defective
 Fehler O2-S007: Sonstiges (unter Angabe in Bemerkung) / Others (see remark)

Fehler O2-S002: Signal instabil / Signal not stable
 Fehler O2-S004: Signal 0mV / Signal 0mV
 Fehler O2-S006: Elektrolyt Austritt / Electrolyte leakage

**BOX:841**

Manufacturer RMA : 300248599

☒ Repaired ☐ No Fault Found

Returned Barcode

Tick All Replaced

Stock Ref	Sup Ref	B/C	S/N	Fault	Replaced	No Fault Found	Repaired	Credited	Out Warranty	Notes
8010004		1642209	JJ127842	Unknown Fault Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1660040	JJ128600	No Output Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1663434	JJ128951	High Output Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1692519	JJ130565	Unknown Fault Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1692546	JJ130592	Unknown Fault Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1686635	JJ130696	Non Liner Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1686649	JJ130710	Non Linier Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1686782	JJ130843	Non Linier Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1686989	JJ131050	Non Liner Country of Origin:	☐	☐	☐	☒	☐	requested update by email 23/02/2022

				Germany Customs Value:5.00 Euro						
8010004		1737548	JJ132047	Low Output Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1737584	JJ132083	Unknown Fault Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1851814	JJ133916	Low Output Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
8010004		1851891	JJ133993	Non Liner Country of Origin: Germany Customs Value:5.00 Euro	☐	☐	☐	☒	☐	requested update by email 23/02/2022
Update										