

Service Repair Sheet SRS68096

Date Promised to Return: 01 Jan 1970 0

Contact Name

Apostolos Atsalakis

Company/ Hospital Name

Xhale

Department

Position

Direct Phone

General Phone

00302109531294

Opera Account

00006401

Email

apostolos@endomedical.co

Order Number

Date Received

05/Jan/2022

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Warranty

05/Jan/2022 Catherine Spence

05/Jan/2022 Catherine Spence

7 UFO sensors received, out of these 7 of them are from RVM134513-1 from 16/12/2021 which was a replacement order(check with Steve Nixon about these.

S/N 689220,689223-689224,289228,689230,689233,689236)

05/Jan/2022 Catherine Spence

received on DHL AWB7354542300

05/Jan/2022 Philip Crossley

They are in my room. I cannot test these.

05/Jan/2022 Catherine Spence

3 units do not have the wings on the sensors

05/Jan/2022 Catherine Spence

Steve Nixon aware these are here.

05/Jan/2022 Catherine Spence

1st unit has been made and this repair is now in testing

05/Feb/2022 Catherine Spence

sted see report attached to this srs

05/Feb/2022 Catherine Spence

needed to remove the duplicate line for S/N 684376 error

05/Feb/2022 Catherine Spence

waiting on new stock to arrive , also waiting on report from Teledyne on other sensors that have already been returned from other RS's, Steve Nixon to advise

05/Feb/2022 Catherine Spence

ingineers room, waiting for replacements

05/Mar/2022 Catherine Spence

noticed on second checking that S/N 672028 has a broken clip

05/Mar/2022 Robert Connor

removed duplicate serial number 684376

05 / 03 / 2022 Catherine Spence

move to new srs due to broken clip

move SRN34512 From SRS68036 To SRS68095

05 / 03 / 2022 Catherine Spence

moved to another SRS waiting for replacement

move SRN34528 From SRS68036 To SRS68096

move SRN34530 From SRS68036 To SRS68096

move SRN34531 From SRS68036 To SRS68096

move SRN34532 From SRS68036 To SRS68096

move SRN34533 From SRS68036 To SRS68096

move SRN34534 From SRS68036 To SRS68096

move SRN34536 From SRS68036 To SRS68096

move SRN34537 From SRS68036 To SRS68096

move SRN34538 From SRS68036 To SRS68096

move SRN34539 From SRS68036 To SRS68096

move SRN34540 From SRS68036 To SRS68096

Ready For quote

Repair Complete Signed

CANEON 14.3.22


SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34528	Oxygen Sensor	0110081	684376	Yes
SRN34530	Oxygen Sensor	0110081	684380	Yes
SRN34531	Oxygen Sensor	0110081	684381	Yes
SRN34532	Oxygen Sensor	0110081	684389	Yes
SRN34533	Oxygen Sensor	0110081	684399	Yes
SRN34534	Oxygen Sensor	0110081	684407	Yes
SRN34536	Oxygen Sensor	0110081	684441	Yes
SRN34537	Oxygen Sensor	0110081	689220	Yes
SRN34538	Oxygen Sensor	0110081	689223	Yes
SRN34539	Oxygen Sensor	0110081	689224	Yes
SRN34540	Oxygen Sensor	0110081	689228	Yes
SRN34541	Oxygen Sensor	0110081	689230	Yes
SRN34542	Oxygen Sensor	0110081	689233	Yes
SRN34543	Oxygen Sensor	0110081	689236	Yes

0140013 x 14 FOC
old S/N, SRS, SRN.

0110081 x 14 FOC
New S/N's, SRS, SRN.

0140014 x 2 FOC
Not under warranty.
Returning as agreed with Apostolos Atsalakis
S/N 689275 SRS 68094, SRN 34611.
S/N 672028 SRS 68095, SRN 34512.

UPS x 1 FOC.



Warning No company id linked:

Enter CID Number

Link Company ID

SRS68094

[Print Barcodes](#)[Print A4 Sheet](#)[Split Items into Different SRS Numbers](#)

Handle with care

Add Items to Supplier Returns Box

Add

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System
will apply to all items on srs

Add notes to SRS

Upload Document to SRS

ADD
DOCUMENT
TO SRS :
Document
Description

Choose a file to upload: Choose file No file chosen

Next

Add Notes

Service Repair Sheet 68094		Notes
Company / Hospital	XHALE S.A.	12/Jan/2022 Robert Connor
Contact Name	Apostolos Atsalakis	12/Jan/2022 Robert Connor
Department		Returning 77 x UFO 130-2
Position		12/Jan/2022 Robert Connor
Company Phone	+30 693 660 9908	Received 77 x UFO 130-2, cell s/n 689725 damaged due to negligent packing by the customer, see attached photo.
Direct Phone		13/Jan/2022 Catherine Spence
Opera Account	00006401	34 units do not have the end wings on the sensors
Email	apostolos@endomedical.co	21/Jan/2022 Catherine Spence
Order Number		This repair is with Derek Lamb and is being tested. Also given a new stock item S/N 703702 scanned to DL. CG 21/01/2022
Viamed ORD Number		25/Jan/2022 Catherine Spence
Date Received Into building	12 Jan 2022	Derek testing
Type	Warranty	25/Jan/2022 Catherine Spence
Issues?		Test unit made and this repair is now being fully tested
		26 /01 / 2022 Derek Lamb
		First 25 been tested and replaced
		Move SRN34553 From SRS68041 To SRS68055
		Move SRN34554 From SRS68041 To SRS68055
		Move SRN34555 From SRS68041 To SRS68055
		Move SRN34556 From SRS68041 To SRS68055
		Move SRN34557 From SRS68041 To SRS68055
		Move SRN34558 From SRS68041 To SRS68055
		Move SRN34559 From SRS68041 To SRS68055
		Move SRN34560 From SRS68041 To SRS68055
		Move SRN34561 From SRS68041 To SRS68055
		Move SRN34562 From SRS68041 To SRS68055
		Move SRN34563 From SRS68041 To SRS68055
		Move SRN34564 From SRS68041 To SRS68055
		Move SRN34565 From SRS68041 To SRS68055
		Move SRN34566 From SRS68041 To SRS68055
		Move SRN34567 From SRS68041 To SRS68055
		Move SRN34568 From SRS68041 To SRS68055
		Move SRN34569 From SRS68041 To SRS68055
		Move SRN34570 From SRS68041 To SRS68055
		Move SRN34571 From SRS68041 To SRS68055
		Move SRN34572 From SRS68041 To SRS68055
		Move SRN34573 From SRS68041 To SRS68055
		Move SRN34574 From SRS68041 To SRS68055

Move SRN34575 From SRS68041 To SRS68055
 Move SRN34576 From SRS68041 To SRS68055
 Move SRN34577 From SRS68041 To SRS68055

05/Feb/2022 Catherine Spence
 Test results for these sensors are attached to this srs
 07/Feb/2022 Philip Crossley
 All tested now
 09/Feb/2022 Catherine Spence
 waiting on new stock to arrive , also waiting on report from Teledyne on other sensors
 that have already been returned from other SRS's, Steve Nixon to advise
 16/Feb/2022 Catherine Spence
 engineers room
 22 /02 / 2022 Catherine Spence
 Moving from SRS68041 to new SRS for replacement purposes as part of a part
 shipment. cg 20220222
 Move SRN34578 From SRS68041 To SRS68085
 Move SRN34579 From SRS68041 To SRS68085
 Move SRN34580 From SRS68041 To SRS68085
 Move SRN34581 From SRS68041 To SRS68085
 Move SRN34582 From SRS68041 To SRS68085
 Move SRN34583 From SRS68041 To SRS68085
 Move SRN34584 From SRS68041 To SRS68085

 03 /03 / 2022 Catherine Spence
 Moving to new SRS due to connector broken
 Move SRN34611 From SRS68041 To SRS68094

Items for Repair

...

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN34611	Oxygen Sensor	0110081	1903362	689275	Oxygen sensor, UFO 130-2	No	No	Unfinished		00:00

Currently Viewing ITEM SRN34611 Oxygen Sensor 0110081 689275 Oxygen sensor, UFO 130-2

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

0140014 x 1 FOC
 SIN, SRS, SRN

please see combined
 order on SRS 68096.
 cg 14.3.22



Warning No company id linked:

Enter CID Number

Link Company ID

SRS68095

Print Barcodes

Print A4 Sheet

Split Items into Different SRS Numbers

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

Add Notes

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: <input type="button" value="Choose file"/> No file chosen
	Next

Service Repair Sheet 68095		Notes
Company / Hospital	Xhale	05/Jan/2022 Catherine Spence
Contact Name	Apostolos Atsalakis	05/Jan/2022 Catherine Spence 46 UFO sensors received, out of these 7 of them are from RVM134513-1 from 16/12/2021 which was a replacement order(check with Steve Nixon about these.
Department		(S/N 689220,689223-689224,289228,689230,689233,689236)
Position		05/Jan/2022 Catherine Spence Received on DHL AWB7354542300
Company Phone	00302109531294	12/Jan/2022 Philip Crossley They are in my room. I cannot test these.
Direct Phone		13/Jan/2022 Catherine Spence 39 units do not have the wings on the sensors
Opera Account	00006401	21/Jan/2022 Catherine Spence Steve Nixon aware these are here.
Email	apostolos@endomedical.co	25/Jan/2022 Catherine Spence Test unit has been made and this repair is now in testing
Order Number		05/Feb/2022 Catherine Spence tested see report attached to this srs
Viamed ORD Number		09/Feb/2022 Catherine Spence need to remove the duplicate line for S/N 684376 error
Date Received Into building	05 Jan 2022	09/Feb/2022 Catherine Spence waiting on new stock to arrive , also waiting on report from Teledyne on other sensors that have already been returned from other SRS's, Steve Nixon to advise
Type	Warranty	16/Feb/2022 Catherine Spence engineers room, waiting for replacements
Issues?		02/Mar/2022 Catherine Spence noticed on second checking that S/N 672028 has a broken clip
		03/Mar/2022 Robert Connor Removed duplicate serial number 684376
		03 /03 / 2022 Catherine Spence Move to new srs due to broken clip
		Move SRN34512 From SRS68036 To SRS68095

Items for Repair

...

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN34512	Oxygen Sensor	0110081	1887493	672028	Oxygen sensor, UFO 130-2	No	No	Unfinished		00:00
SRN34512 Customer Notes: Unstable output										

Currently Viewing ITEM SRN34512 Oxygen Sensor 0110081 672028 Oxygen sensor, UFO 130-2

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	02/Mar/2022 Catherine Spence Clip where wing should be is broken 02/Mar/2022 Catherine Spence New Warranty Flagged OFF Part of clip is broken	Non added Yet

0140014 x 1 FOC
S/N, SRS, SRN

Please see combined
order on
SRS 68096 cg 14.3.22.