Service Repair Sheet 68106

Contact Name Glenn Friedman
Company/ Hospital Name Cryptonfix Ltd
Direct Phone 07540 624242
General Phone 07540624242
Opera Account 00020044

Email cryptonfix@gmail.com

Date Received 24/Mar/2022 Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN34912 0110182 V100687 Oxygen Sensor End Of Life
Time :0 Hour(s)

The Oxygen sensor - Automotive R-22AVG is out of warranty and has not been replaced.

Disposed of as agreed with customer

Repair Ref S/N Equipment Type Under Warranty

SRN34913 0110182 V104311 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105234.

Repair Ref S/N Equipment Type Under Warranty

SRN34914 0110182 V104352 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105235.

Repair Ref S/N Equipment Type Under Warranty

SRN34915 0110182 V104356 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105236.

Repair Ref S/N Equipment Type Under Warranty

SRN34916 0110182 V104359 Oxygen Sensor Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105237.

Service Repair Sheet 68106

Contact Name Glenn Friedman
Company/ Hospital Name Cryptonfix Ltd
Direct Phone 07540 624242
General Phone 07540624242
Opera Account 00020044

Email cryptonfix@gmail.com

Date Received 24/Mar/2022 Booked in By Robert Connor

Repair Ref S/N Equipment Type Under Warranty

SRN34917 0110182 V104363 Oxygen Sensor

Time :0 Hour(s)
Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105238.

Repair Ref S/N Equipment Type Under Warranty

SRN34918 0110182 V104364 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105239.

Repair Ref S/N Equipment Type Under Warranty

SRN34919 0110182 V104375 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105240.

Repair Ref S/N Equipment Type Under Warranty

SRN34920 0110182 V104380 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105241.

Repair Ref S/N Equipment Type Under Warranty

SRN34921 0110182 V104395 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105242.

Service Repair Sheet 68106

Contact Name Glenn Friedman
Company/ Hospital Name Cryptonfix Ltd
Direct Phone 07540 624242
General Phone 07540624242
Opera Account 00020044

Email cryptonfix@gmail.com

Date Received 24/Mar/2022 Booked in By Robert Connor

Repair Ref S/N Equipment Type Under Warranty

SRN34922 0110182 V104398 Oxygen Sensor Time :0 Hour(s)

Ports Ports and

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105243.

Repair Ref S/N Equipment Type Under Warranty

SRN34923 0110182 V104400 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105244.

Repair Ref S/N Equipment Type Under Warranty

SRN34924 0110182 V104414 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105245.

Repair Ref S/N Equipment Type Under Warranty

SRN34925 0110182 V104426 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105246.

Repair Ref S/N Equipment Type Under Warranty

SRN34926 0110182 V104429 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182

The Oxygen sensor - Automotive R-22AVG has been replaced under warranty with SN:V105247.