



Warning No company id linked:

Enter CID Number

Link Company ID

SRS68131

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

ADD
DOCUMENT
TO SRS :
Document
Description

Choose a file to upload: No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68131		Notes	
Company / Hospital	Bavaria Blue for Safari	12/Apr/2022 Robert Connor	
Contact Name	Paul Cooper	12/Apr/2022 Robert Connor	
Department		Received 1 x tek ox s/nTX 0932 for service, and wants to buy another	
Position		<i>LINKED ISSUE NOTES:</i>	
Company Phone	0115 943 1430	257398 :	
Direct Phone	07966 142380	AutoGenerated Issue SRS68131 Appears to be Complete	
Opera Account	BAVARIA	19 Apr 2022 Catherine Spence	
Email		vandagraph repair	
Order Number			
Viamed ORD Number			
Date Received Into building	12 Apr 2022		
Type	Quote Before Repair		
Issues?	257398		

Items for Repair

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN34944	Oxygen Analyser TEK-OX	9710203	407674	0932	Oxygen Analyser TEK-OX	No	No	Serviced	Calibration Problem	00:30

Currently Viewing ITEM SRN34944 Oxygen Analyser TEK-OX 9710203 0932 Oxygen Analyser TEK-OX

Create a Meeting Issue

Items Requested for Repair					Item notes	Engineer Notes	Notes To Customer
Item	Qty	By	Date Requested	Status	The Tek-Ox analyser has been tested. The unit is working as expected. The R-17VAN Oxygen sensor has been replaced with SN:105878. The batteries have been replaced.	14/Apr/2022 Michael Green The Tek-Ox analyser has been tested. The unit is working as expected. The sensor has expired. The batteries should be replaced.	The Tek-Ox analyser has been tested. The unit is working as
0110217	1	Michael Green	14/Apr/2022	completed			

14/Apr/2022 Michael Green The Tek-Ox analyser has been tested. The unit is working as expected. The R-17VAN Oxygen sensor has been replaced with SN:105878. The batteries have been replaced.	expected. The R-17VAN Oxygen sensor has been replaced with SN:105878. The batteries have been replaced.
---	---

0110217 105878 1948090

