

**COMPANY OPERATING PROCEDURES****Maxtec Max-02 (PN 0110402)  
O<sub>2</sub> Sensor Test Procedure**

VM3/COP/37.13

Date: 3-Feb-03

Revision date: 25-May-11

Issue: 3

**Test & Equipment Required**

Visual check only - no test equipment required.

Output specification as in document: (VM3COP37.00, column (i)).

**Method.**

1. Open the packaging and remove the O<sub>2</sub> sensor.
2. Check the O<sub>2</sub> sensor for damage and signs of leaking electrolyte.
3. Remove the O<sub>2</sub> sensor specification leaflet and discard.
4. Label with Viamed stickers if appropriate.
5. Reseal in serial numbered packet, integrity seal the edge of the packet with initialed and dated Viamed sticker and re-box.
6. Ensure the O<sub>2</sub> sensor is booked out in the stock books.