

Service Repair Sheet SRS68154
Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Date Promised to Return: 01 Jan 1970 -3600
Sue Francis
Emergency Medical Retrieval Transfer Service (EMRTS)

Admin Assistant
0300 3000 058
0300 3000 057
00000159
Sue.Francis@wales.nhs.uk

11/May/2022
Robert Connor
Viamed
Quote

Notes 06/May/2022 Sophie Lines

06/May/2022 Sophie Lines

Defective screen display - S/N: A160813005

11/May/2022 Robert Connor

Received 1 x VM2500-S, s/n A1608130005, with 4 x AA battery, silicone cover, 2 unused sampling lines and viral filter, and orange fabric carry case.

16/May/2022 Catherine Spence

Missed off SRS 1 x finger probe S/N EFG01363

Ready For quote

CGreen 18.5.22.

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35042	Capnograph	4410520	A1608130005	22
SRN35050	Pulse Oximetry Finger Sensor	0014750	EFG01363	22

4440000 x ^{0.5} @ £90 per hr = £45
S/N, SRS, SRN.

4430120 x 1 @ £80.
SRS, SRN.


0040001 x 1 @ £0.
S/N, SRS, SRN
No fault found.

UPS x 1 @ £10.

Catherine Spence Required Reading 21 Issues 15 Unread 14 ISO Tasks | H/W:

Future Active Users 23.00 °C

▼ Search



Select Currency

Pounds| Euros| Usd

Repair SRS68154 Values in Pounds @ £1: £1.00

SRN35042	Capnograph	4410520			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		4430120	1	£72.00	£72.00
		4440000	0.5	£90.00	£45.00
				Parts Cost	£117.00

£80.00 cgy 18.5

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent

EMRTS Cymru - Electromed Fault Report
Database ID: -MtChH_I3Us1y0ND-Fxj



Fault Report

ID: -MtChH_I3Us1y0ND-Fxj Date: 12/01/22 - 09:47
Base: H61 - Caernarfon Reported by: John Adams
Location:
Device was in Wamed Module 22 - Barcode: 00039

Electromed ID: 00132

Manufacturer: Wamed

Model: VM-2500-S

Serial: A160813005

Fault Details

Damaged/Mechanical: YES Software Issue: NO

Fault Description:

Screen display unreadable. No visible screen damage. Potential that screen has had force directly applied to it whilst in the bag.

Defect handed over by another member of the team. Device taken out of service and replaced with another unit from the major incident stores.

Case Details

Near Miss: NO

Patient Harm: NO