


COMPANY OPERATING PROCEDURE**Q.A. - Packing Checklist Procedure Light Shield
VM3/COP/52.03**

Date: 29-Sep-03

Revision Date:11-Jul-11

Issue: 1

1. Unpack the Light shield from its original packing, and check that:
 - a. The product is the correct item
 - b. The product is the correct configuration:
 - i) PP Full Amber Hood needs CE0086
 - ii) PP Semi Hood needs CE
 - iii) PP Open Light Shield needs CE
 - iv) Special Full version needs CE0086 Special Open needs CE



Ensure correct CE mark label is attached to Light Shield panel and is incorporated on the User Insert

2. Check the product to ensure

that there are no sharp edges.

3. Check that there are no scratches on the product.
4. Check the neck aperture to ensure that there are no sharp edges.
5. Add the appropriate labels.

Light shield Part no	Label Part Number
PP8400	0195001
PP8509	0195001
PP8510	0195001
PP8533	0195001
PP8559	0195001
PP8560	0195001
PP8689	0195001
PP8562	0195001

6. Add the insert leaflet No 0490049
7. Clean the product and repack.
8. Ensure that there is an adequate amount of packaging material around the product prior to taping up the box.