



Zoey Teal <viamed.zoey.teal@gmail.com>

Fwd: Replacement oxygen sensors

1 message

Steve Nixon <office@viamed.co.uk>
 Reply-To: steve.nixon@viamed.co.uk
 To: office@vmsecure.me.uk

Wed, Jun 8, 2022 at 12:17 PM

VST customer - JJ-CCR

Please generate a no charge order for sensors to JJ-CCR

13 x 8010004 oxygen sensors £0.00

Add notes:

Sensors to replace the following

Serial Number	SRS Number	SRN Number	Company	
JJ132225	SRS68038	SRN34544	JJ-CCR ApS	NFF*
JJ132232	SRS68038	SRN34545	JJ-CCR ApS	NFF*
JJ127842	SRS68050	SRN34637	JJ-CCR ApS	Out of warranty
JJ128600	SRS68050	SRN34638	JJ-CCR ApS	Out of warranty
JJ128951	SRS68050	SRN34639	JJ-CCR ApS	Out of warranty
JJ130565	SRS68050	SRN34640	JJ-CCR ApS	No output
JJ130592	SRS68050	SRN34641	JJ-CCR ApS	NFF*
JJ130696	SRS68050	SRN34642	JJ-CCR ApS	Unstable output signal
JJ130710	SRS68050	SRN34643	JJ-CCR ApS	NFF*
JJ130843	SRS68050	SRN34644	JJ-CCR ApS	NFF*
JJ131050	SRS68050	SRN34645	JJ-CCR ApS	NFF*
JJ132047	SRS68050	SRN34646	JJ-CCR ApS	Low output
JJ132083	SRS68050	SRN34647	JJ-CCR ApS	NFF*
JJ133916	SRS68050	SRN34648	JJ-CCR ApS	Low output
JJ133993	SRS68050	SRN34649	JJ-CCR ApS	NFF*
JJ134205	SRS68061	SRN34668	Narked at 90 Ltd	Unstable output signal

The ones out of warranty will not be replaced.

*Eight of the sensors were assessed and no fault found. However, we will replace these as a good-will gesture.

Please note that JJ134205 was returned to us via Narked at 90. We will send the replacement to yourselves, will you then please ship a replacement sensor to Narked at 90?

----- Forwarded message -----

From: **Anita** <anita@jj-ccr.com>
 Date: Wed, 8 Jun 2022 at 08:05
 Subject: Re: Replacement oxygen sensors
 To: <steve.nixon@viamed.co.uk>

Hi Steve

Thanks you so much
I will make sure we replace one cell to Narked

Kind regards

Anita Marshall

JJ-CCR ApS · Dyrlevvej 11 · 4720 Presto · Denmark

Phone direct: +45 22 55 97 97

Email: anita@jj-ccr.com

Web: <https://jj-ccr.com>

Den 6. juni 2022 kl. 16.27.53 +02.00, skrev Steve Nixon <office@viamed.co.uk>:

Hi Anita

We will send you 13 replacement 8010004 oxygen sensors to cover the sensors as listed below.

The ones out of warranty will not be replaced.

Eight of the sensors were assessed and no fault found. However, we will replace these as a good-will gesture.

Please note that JJ134205 was returned to us via Narked at 90. We will send the replacement to yourselves, will you then please ship a replacement sensor to Narked at 90?

Serial Number	SRS Number	SRN Number	Company	
JJ132225	SRS68038	SRN34544	JJ-CCR ApS	NFF*
JJ132232	SRS68038	SRN34545	JJ-CCR ApS	NFF*
JJ127842	SRS68050	SRN34637	JJ-CCR ApS	Out of warranty
JJ128600	SRS68050	SRN34638	JJ-CCR ApS	Out of warranty
JJ128951	SRS68050	SRN34639	JJ-CCR ApS	Out of warranty
JJ130565	SRS68050	SRN34640	JJ-CCR ApS	No output
JJ130592	SRS68050	SRN34641	JJ-CCR ApS	NFF*
JJ130696	SRS68050	SRN34642	JJ-CCR ApS	Unstable output signal
JJ130710	SRS68050	SRN34643	JJ-CCR ApS	NFF*
JJ130843	SRS68050	SRN34644	JJ-CCR ApS	NFF*
JJ131050	SRS68050	SRN34645	JJ-CCR ApS	NFF*
JJ132047	SRS68050	SRN34646	JJ-CCR ApS	Low output
JJ132083	SRS68050	SRN34647	JJ-CCR ApS	NFF*
JJ133916	SRS68050	SRN34648	JJ-CCR ApS	Low output
JJ133993	SRS68050	SRN34649	JJ-CCR ApS	NFF*
JJ134205	SRS68061	SRN34668	Narked at 90 Ltd	Unstable output signal

Regards

--

Steve

Steve Nixon
Director - Viamed Ltd.

Office: +44 (0)1535 634542
Mobile: +44 (0)7850 252267

GDPR / Privacy Policy available at www.viamed.co.uk/policy

.

--

Steve

Steve Nixon
Director - Viamed Ltd.

Office: +44 (0)1535 634542
Mobile: +44 (0)7850 252267

GDPR / Privacy Policy available at www.viamed.co.uk/policy

.