



# Tofo Scuba

CID9216 Opera TOFO Type:Vandagraph Trade

Tofo Scuba Praia do Tofo, , Inhambane, , Mozambique

Tel +258 29 329030

Log Call

Proforma

Account Home

Main Details

Account Memos

Sales History

Stock References

Customer Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

## SRS68158

[Print Barcodes](#)[Print A4 Sheet](#)[Split Items into Different SRS Numbers](#)

### Upload Document to SRS

|                                               |                                                                                    |
|-----------------------------------------------|------------------------------------------------------------------------------------|
| ADD DOCUMENT TO SRS :<br>Document Description | Choose a file to upload: <input type="button" value="Choose file"/> No file chosen |
|                                               | <input type="text"/>                                                               |
| <input type="button" value="Next"/>           |                                                                                    |

Handle with care

Add Items to Supplier Returns Box

 

- ☐ Return for Credit / Return to Stock  
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.  
- will apply to all items on srs

Add notes to SRS

  


| Service Repair Sheet 68158  |                     | Notes                                                                                                                        |
|-----------------------------|---------------------|------------------------------------------------------------------------------------------------------------------------------|
| Company / Hospital          | Tofo Scuba          | 10/May/2022 Ryan Swaine                                                                                                      |
| Contact Name                | Ross                | 10/May/2022 Ryan Swaine                                                                                                      |
| Department                  |                     | VN202 repaired after a battery leak in 2021 (SRS67904). Having another problem, presumably not turning on. To test and quote |
| Position                    |                     | 31/May/2022 Robert Connor                                                                                                    |
| Company Phone               | +258 29 329030      | Received 1 x VN202 s/n 00770, with coiled cable 0000495                                                                      |
| Direct Phone                | 00258843733074      | <b>LINKED ISSUE NOTES:</b>                                                                                                   |
| Opera Account               | TOFO                | <a href="#">262726</a> :                                                                                                     |
| Email                       | info@tofoscuba.com  | AutoGenerated Issue SRS68158 Appears to be Complete                                                                          |
| Order Number                |                     |                                                                                                                              |
| Viamed ORD Number           |                     |                                                                                                                              |
| Date Received Into building | 31 May 2022         |                                                                                                                              |
| Type                        | Quote Before Repair |                                                                                                                              |
| Issues?                     | 262726              |                                                                                                                              |

### Items for Repair

... ..

| SRN                                                                                                                                                                                                         | Equipment             | Stock Reference | Barcode                                                                                  | Serialnumber | Description                  | Warranty New | Warranty Repair | Status           | Repair Code                     | Time (H:M) |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|-----------------|------------------------------------------------------------------------------------------|--------------|------------------------------|--------------|-----------------|------------------|---------------------------------|------------|
| <a href="#">SRN35074</a>                                                                                                                                                                                    | Oxygen Analyser VN202 | 7910100         |  870797 | 00770        | VN202mkII - Auto Switch Off  | No           | No              | No Fault Found   | No Fault Found                  | 00:00      |
| SRN35074 Engineer Notes: <b>INTERNAL NOTES not for customer discussion</b><br>10/Jun/2022 Michael Green<br>The VN202 Oxygen analyser has been tested. No fault was found.                                   |                       |                 |                                                                                          |              |                              |              |                 |                  |                                 |            |
| <a href="#">SRN35075</a>                                                                                                                                                                                    | Oxygen Monitor Cable  | 0131203         |  459694 | 0000495      | Oxygen Sensor Cable - Yellow | No           | No              | Unable to Repair | Cable Intermittent Open Circuit | 00:00      |
| SRN35075 Engineer Notes: <b>INTERNAL NOTES not for customer discussion</b><br>10/Jun/2022 Michael Green<br>The Oxygen sensor cable has been tested. The cable has failed and replacement has been supplied. |                       |                 |                                                                                          |              |                              |              |                 |                  |                                 |            |

**Currently Viewing ITEM SRN35074 Oxygen Monitor Cable 0131203 0000495 Oxygen Sensor Cable - Yellow**

[Create a Meeting Issue](#)

| Items Requested for Repair | Item notes                                                                                      | Engineer Notes                                                                                                                | Notes To Customer                                                                               |
|----------------------------|-------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|
|                            | The Oxygen sensor cable has been tested. The cable has failed and replacement has been supplied | 10/Jun/2022 Michael Green<br>The Oxygen sensor cable has been tested. The cable has failed and replacement has been supplied. | The Oxygen sensor cable has been tested. The cable has failed and replacement has been supplied |

↓