

Viamed Returns Shipping Invoice

Delivery Address:

Honeywell Healthcare Solutions GmbH RMA: 300289517

Karen Bull

Alter Holzhafen 18

Wismar

Germany

D-23966

Eori DE3174778

0049 3841 360204

Date: 09 Sep 2025

Viamed RN: RTS11001046

Shipper Address:

Viamed

15 Station Road

Cross Hills

Keighley

West Yorkshire

BD20 7DT

+44 (0) 1535 634542

+44 (0) 1535 635582

info@viamed.co.uk

Returns Under Warranty Value for Customs : 85.00 eurosSee Attached Listing for Serial numbers and Faults

Part Number	P/N / Value	Description	Quantity
0110040	0110040	E1002731 OOM110 Oxygen Sensor	17
	Tariff Code: 9019200000		

Part Number	Serial Number	RMA	Fault Description
0110040	V108258	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108446	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108447	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108449	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108469	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108470	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108472	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108473	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108474	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108475	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108476	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108478	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108479	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108480	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108481	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108482	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro
0110040	V108483	300289517	Manufacturing defect, leaking gas through the connector Country of Origin: Germany Customs Value; 5.00 euro