

Vandagraph Returns Shipping Invoice

Delivery Address:

Honeywell Healthcare Solutions GmbH RMA: 300278404

Andre Schliemann

Alter Holzhafen 18

Wismar

Germany

D-23966

Eori DE3174778

0049 3841 360204

Date: 23 Aug 2024

Vandagraph RN: RTS2100997

Shipper Address:

Vandagraph

15 Station Road

Cross Hills

Keighley

West Yorkshire

BD20 7DT

44 (0) 1535 634900

44 (0) 1535 635582

info@vandagraph.co.uk

Returns Under Warranty Value for Customs : 3535 euro

See Attached Listing for Serial numbers and Faults

Part Number

0110301

P/N / Value

0110301

Tariff Code: 90271010

Description

Oxygen sensor Type 22. P/N 30

Quantity

707

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

Part Number	Serial Number	RMA	Fault Description
0110301	D112251	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112252	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112253	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112254	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112255	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112256	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112257	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112258	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112259	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112260	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112261	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112262	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112263	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112264	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112265	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112266	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112267	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112268	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro
0110301	D112269	300278404	RMA Box: 997 Linearity Error, Country of Origin: Germany Customs Value: 5.00 Euro