VST Returns Shipping Invoice

Delivery Address: Date: 25 Oct 2024 Shipper Address:

Honeywell Healthcare Solutions GmbH RMA: 300280270 VST

Jessica Wagner VST RN: RTS31001004 15 Station Road

Alter Holzhafen 18 Cross Hills Wismar Keighley

Germany West Yorkshire BD20 7DT

Eori DE3174778 +44 (0) 1535 634900 0049 3841 360204 +44 (0) 1535 635582

info@vandagraphst.com

Returns Under Warranty Value for Customs : 1250 Euro See Attached Listing for Serial numbers and Faults

Part Number P/N / Value Description Quantity 8010020 Source Sensor - type 22D 250

Tariff Code: 9019209000

Part Number	Serial Number	RMA	Fault Description
8010020	D115058	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with 'November' manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115059	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115060	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115061	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115062	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115063	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115064	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115065	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115066	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115067	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115068	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115069	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115070	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115071	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115072	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115073	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115074	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115075	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115076	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115077	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115078	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115079	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115080	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115081	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115082	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115083	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115084	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115085	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115086	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115087	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115088	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115089	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115090	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115091	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115092	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115093	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115094	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115095	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115096	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115097	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115098	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115099	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115100	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115101	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115102	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115103	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115104	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115105	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115106	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115107	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115108	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115109	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115110	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115111	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115112	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115113	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115114	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115115	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115116	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115117	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115118	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115119	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115120	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115121	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115122	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115123	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115124	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115125	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115126	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115127	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115128	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115129	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115130	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115131	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115132	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115133	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115134	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115135	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115136	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115137	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115138	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115139	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115140	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115141	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115142	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115143	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115144	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115145	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115146	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115147	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115148	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115149	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115150	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115151	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115152	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115153	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115154	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115155	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115156	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115157	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115158	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115159	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115160	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115161	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115162	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115163	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115164	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115165	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115166	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115167	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115168	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115169	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115170	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115171	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115172	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115173	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115174	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115175	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115176	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115177	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115178	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115179	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115180	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115181	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115182	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115183	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115184	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115185	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115186	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115187	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115188	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115189	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115190	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115191	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115192	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115193	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115194	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115195	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115196	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115197	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115198	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115199	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115200	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115201	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115202	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115203	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115204	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115205	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115206	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115207	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115208	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115209	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115210	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115211	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115212	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115213	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115214	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115215	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115216	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115217	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115218	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115219	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115220	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115221	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115222	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115223	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115224	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115225	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115226	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115227	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115228	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115229	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115230	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115231	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115232	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115233	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115234	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115235	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115236	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115237	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115238	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115239	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115240	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115241	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115242	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115243	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115244	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115245	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115246	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115247	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115248	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115249	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115250	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115251	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115252	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115253	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115254	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115255	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115256	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115257	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115258	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115259	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115260	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115261	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115262	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115263	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115264	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115265	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115266	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115267	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115268	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115269	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115270	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115271	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115272	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115273	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115274	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115275	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115276	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115277	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115278	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115279	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115280	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115281	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115282	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115283	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115284	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115285	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115286	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115287	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115288	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115289	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115290	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115291	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115292	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115293	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115294	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115295	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115296	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115297	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115298	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115299	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115300	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115301	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115302	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115303	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro

Part Number	Serial Number	RMA	Fault Description
8010020	D115304	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115305	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115306	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro
8010020	D115307	300280270	As agreed with Jessica Wagner and Marko Sprossel: 250 x E1002737, OOD103 returned for retesting and reprocessing. To be relabelled with November manufactured date. Sensors to be returned back to VST on no-charge invoice as the original invoice has been paid. Country of Origin: Germany Customs Value: 5.00 Euro