

## Viamed Production Sheet PS3646 U Drive: WVM3646.pdf

Advanced Ref 1715857385
Started:16/May/2024 By Catherine Spence Quantity 18
8000004 Cable assembly for oxygen sensor 8010004
Produced By Michael Green

Q.A. By \_\_\_\_\_ Boxed By \_\_\_\_\_

1						
Barcode(2453352)	PR03646A10	Produced [ ]	Q.A. [ ]	Boxed Ready	For S	sale[]
Barcode(2453353)	PR03646A11	Produced [ ]	Q.A. [ ]	Boxed Ready	For S	Sale[]
Barcode(2453354)	PR03646A12	Produced [ ]	Q.A. [ ]	Boxed Ready	For S	Sale[]
 Barcode(2453355)						
 Barcode(2453356)						
 Barcode(2453357)						
 Barcode(2453358)						
 Barcode(2453359)						
 Barcode(2453360)						
 Barcode(2453361)						
 Barcode(2453362)						
 Barcode(2453363)						
 Barcode(2453364)						
,			- <b>-</b>	•		



## Viamed Production Sheet PS3646

U Drive: WVM3646.pdf Advanced Ref 1715857385 Started:16/May/2024 By Catherine Spence Quantity 18 8000004 Cable assembly for oxygen sensor 8010004 Produced By Michael Green Q.A. By

Q.A. By \_\_\_\_\_ Boxed By \_\_\_\_\_

