



Steve Nixon &lt;steve.nixon.viamed@googlemail.com&gt;

## Gas leakage, just 1 out of 307

1 message

**Steve Nixon** <steve.nixon@viamed.co.uk>  
Reply-To: steve.nixon@viamed.co.uk  
To: Vasu P Narasimhan <Vasu.Narasimhan@teledyne.com>  
Cc: Kunal Kothari <Kunal.Kothari@teledyne.com>

20 August 2018 at 17:45

Hi Vasu

We have carried out a quick gas leakage test on the full batch of 307 x R-22AHJR sensors

The good news is that there was just the one sensor which didn't have the backing paper removed from the foam adhesive ring.

So, it looks like in reality the issue has hopefully been resolved.

I'll try and get some sensors back that failed in the field.

--  
Steve

Steve Nixon  
Director - Viamed Ltd.

Office: +44 (0)1535 634542  
Mobile: +44 (0)7850 252267