

Test Date 22-Aug-18

Confirmation test that re-pressurization does not affect sensor output



Image1 Disassembled the sensor




Image2 Spacers for applying pressure



Image3 Pressurization to the sensor

Result Pressurization on the sensor does not change the sensor output