

Sensor will not calibrate to 20.9% with Calibration control fully clockwise





Unscrew sensor from Jack plug



Carefully cut the end off the gas barrier bag

And remove the sensor



Insert the Jack plug into the new sensor and screw finger tight



Check Calibration can be set to 20.9%





Dispose of sensor carefully



Return it to Vandagraph when you purchase a replacement

or

Treat it like a battery and dispose of it in accordance with local regulations