

Hospital: Royal Preston

Room: 7

Date: 5/10/20

**Cabinet Body Serial number: D008**

- Check for overall signs of damage Comments ✓
- Check door catch - swivel catch on door ✓
- Check door catch retaining clasp on cabinet ✓
- Check integrity of welds on the door hinges ✓
- Check hinges for damage or deformation ✓
- Check the restraining bars for damage or deformation ✓
- Check the cabinet is securely fixed to wall ✓
- Check medirails and tighten any loose rails ✓
- Check grommets on the hose inlets are in place and intact ✓
- Check the bumper stops that prevent door banging during closing ✓
- Check caution sticker is in place on the platform ✓
- Check bed for damage i.e. cracks, chips ✓
- Check all the bed mounting screws are in place ✓
- Check mattress for damage i.e. tears, split seams ✓

**Tom Thumb - Serial Number: VMEF08**

Minimum reading less 7.85 mbar: 1.9

Adjustable valve 42.1 mbar +/-1: 42.1

Precision Valve 44.1 mbar +/-1: 44.2

Gauge @30cmh2o (28.4-30.4 mbar): 30.1

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

**Date of last hose replacement:**

**Low Suction Controller - Serial number: 031144527**

Change filter assembly ✓

Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

**Date of last hose replacement: 5/10/20**

Check rail clamp is securely attached to suction controller ✓

Replace suction tubing ✓

Replace tapered connector ✓

Check receiving canister for damage, replaced? ✓

**Radiant Warmer Serial number: WDQ059RW**

Is Radiant Warmer hard-wired? ✓ Y

PAT test performed? ✓

**APGAR Timer - Serial number: 00948**

Change batteries ✓

Check storage bins present ✓ - No, not required

Tidy any trailing hoses, using tie-wraps if necessary ✓

Check Operator's Manuals are in place ✓

Clean cabinet with isopropyl alcohol ✓

**Blender Serial number: B1551981**

**Date of last hose replacement: 5/10/20**

@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen

Check Alarm for no Air

Check O2/Air Balance Alarms before output change

Check Duck Bill Valves

Check for Leaks

Blender requires overhaul

Hospital: Royal Preston

Room: 4

Date: 12/10/20

Cabinet Body Serial number: D003

Check for overall signs of damage Comments ✓  
Check door catch - swivel catch on door ✓ - slightly loose, recommend replacement  
Check door catch retaining clasp on cabinet ✓  
Check integrity of welds on the door hinges ✓  
Check hinges for damage or deformation ✓  
Check the restraining bars for damage or deformation ✓  
Check the cabinet is securely fixed to wall ✓  
Check medirails and tighten any loose rails ✓  
Check grommets on the hose inlets are in place and intact ✓  
Check the bumper stops that prevent door banging during closing ✓  
Check caution sticker is in place on the platform ✓  
Check bed for damage i.e. cracks, chips ✓  
Check all the bed mounting screws are in place ✓  
Check mattress for damage i.e. tears, split seams ✓

Tom Thumb - Serial Number: VMEFO1

Minimum reading less 7.85 mbar: 20 mbar

Adjustable valve 42.1 mbar +/-1: 41.2

Precision Valve 44.1 mbar +/-1: 44.4

Gauge @30cmh2o (28.4-30.4 mbar): 29.4

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

Date of last hose replacement:

Low Suction Controller - Serial number: 031180205

Change filter assembly ✓

Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

Date of last hose replacement: 12/10/20

Check rail clamp is securely attached to suction controller ✓

Replace suction tubing ✓

Replace tapered connector ✓

Check receiving canister for damage, replaced? ✓ - OK

Radiant Warmer Serial number: YD2062RW

Is Radiant Warmer hard-wired? ✓ ✓

PAT test performed? ✓ Y

APGAR Timer - Serial number: N/A - Old black type time

Change batteries ✓

Check storage bins present ✗ - Not required

Tidy any trailing hoses, using tie-wraps if necessary ✓

Check Operator's Manuals are in place ✓

Clean cabinet with isopropyl alcohol ✓

Blender Serial number:

Date of last hose replacement:

@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen

Check Alarm for no Air

Check O2/Air Balance Alarms before output change

Check Duck Bill Valves

Check for Leaks

Requires overhaul.

Hospital: Royal Preston

Room: Mat B

Date: 12/10/20

**Cabinet Body Serial number: E347**

Check for overall signs of damage Comments ✓  
Check door catch - swivel catch on door ✓  
Check door catch retaining clasp on cabinet ✓  
Check integrity of welds on the door hinges ✓  
Check hinges for damage or deformation ✓  
Check the restraining bars for damage or deformation ✓  
Check the cabinet is securely fixed to wall ✓  
Check medirails and tighten any loose rails ✓  
Check grommets on the hose inlets are in place and intact ✓  
Check the bumper stops that prevent door banging during closing ✓  
Check caution sticker is in place on the platform ✓  
Check bed for damage i.e. cracks, chips ✓  
Check all the bed mounting screws are in place ✓  
Check mattress for damage i.e. tears, split seams ✓

**Tom Thumb - Serial Number: VMDI25**

Minimum reading less 7.85 mbar: 4.2  
Adjustable valve 42.1 mbar +/-1: 41.2  
Precision Valve 44.1 mbar +/-1: 44.5  
Gauge @30cmh2o (28.4-30.4 mbar): 30.0

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

**Date of last hose replacement:**

**Low Suction Controller - Serial number: 031144519**

Change filter assembly ✓  
Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

**Date of last hose replacement: 12/10/20**

Check rail clamp is securely attached to suction controller ✓  
Replace suction tubing ✓  
Replace tapered connector ✓  
Check receiving canister for damage, replaced? ✓ OK

**Radiant Warmer Serial number: WD2038 RW**

Is Radiant Warmer hard-wired? ✓ Y

PAT test performed? ✓ X

**APGAR Timer - Serial number: -N/A - old style timer**

Change batteries ✓  
Check storage bins present ✓ YES  
Tidy any trailing hoses, using tie-wraps if necessary ✓  
Check Operator's Manuals are in place ✓  
Clean cabinet with isopropyl alcohol ✓

**Blender Serial number: B1551980 - Brought back for overhaul**

**Date of last hose replacement: 12/10/20**

@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen

Check Alarm for no Air

Check O2/Air Balance Alarms before output change

Check Duck Bill Valves

Check for Leaks

Installed blender B1551978. (just overhauled)

Hospital: Royal Preston

Room: BIRTH CENTRE Date: 12/10/20

Cabinet Body Serial number: E357

Check for overall signs of damage Comments ✓  
Check door catch - swivel catch on door ✓  
Check door catch retaining clasp on cabinet ✓  
Check integrity of welds on the door hinges ✓  
Check hinges for damage or deformation ✓  
Check the restraining bars for damage or deformation ✓  
Check the cabinet is securely fixed to wall ✓  
Check medirails and tighten any loose rails ✓  
Check grommets on the hose inlets are in place and intact ✓  
Check the bumper stops that prevent door banging during closing ✓  
Check caution sticker is in place on the platform ✓  
Check bed for damage i.e. cracks, chips ✓ 14"  
Check all the bed mounting screws are in place ✓  
Check mattress for damage i.e. tears, split seams ✓ 14"

Tom Thumb - Serial Number: 0401172

Minimum reading less 7.85 mbar: ✓  
Adjustable valve 42.1 mbar +/-1: 42.5  
Precision Valve 44.1 mbar +/-1: 43.6  
Gauge @30cmh2o (28.4-30.4 mbar): 29.5

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years) ✓

Date of last hose replacement: ~~25/3/19~~ N/A (T1480)

Low Suction Controller - Serial number: 25370002

Change filter assembly ✓  
Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓  
Date of last hose replacement: Check service logs - 25/3/19  
Check rail clamp is securely attached to suction controller ✓  
Replace suction tubing ✓  
Replace tapered connector ✓  
Check receiving canister for damage, replaced? ✓

Radiant Warmer Serial number: 475-3-0314

Is Radiant Warmer hard-wired? ✓ Y  
PAT test performed? ✓

APGAR Timer - Serial number: 00740

Change batteries ✓  
Check storage bins present ✓ Y  
Tidy any trailing hoses, using tie-wraps if necessary ✓  
Check Operator's Manuals are in place ✓  
Clean cabinet with isopropyl alcohol ✓

Blender Serial number: B1404670

Date of last hose replacement: Check service logs - 25/3/19

@20.9: 25 @30: @60: @90: @100: 97 (+/-3)

Check Alarm for no Oxygen  
Check Alarm for no Air  
Check O2/Air Balance Alarms before output change  
Check Duck Bill Valves  
Check for Leaks

Needs flowmeter outlet. - Sorted locally by EBME Dept. ✓

Blender not calibrated, only has range from 25% - 97%.

Installed Blender s/n B1551983 (just overhauled) to allow us to bring back for cal. Note: this one was only due an annual service, parts have been replaced already.

Hospital: ROYAL PRESTON

Room: 3

Date: 14-10-20

Cabinet Body Serial number: D007

Check for overall signs of damage Comments /  
Check door catch - swivel catch on door /  
Check door catch retaining clasp on cabinet /  
Check integrity of welds on the door hinges /  
Check hinges for damage or deformation /  
Check the restraining bars for damage or deformation / — FAILING WELD photo taken.  
Check the cabinet is securely fixed to wall /  
Check medirails and tighten any loose rails /  
Check grommets on the hose inlets are in place and intact /  
Check the bumper stops that prevent door banging during closing /  
Check caution sticker is in place on the platform /  
Check bed for damage i.e. cracks, chips /  
Check all the bed mounting screws are in place /  
Check mattress for damage i.e. tears, split seams /

Tom Thumb - Serial Number: VMEF03 14072

Minimum reading less 7.85 mbar: ~~28.0.4~~

Adjustable valve 42.1 mbar +/-1: ~~41.5~~

Precision Valve 44.1 mbar +/-1: ~~44.0~~

Gauge @30cmh2o (28.4-30.4 mbar): ~~29.9~~

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

Date of last hose replacement:

Low Suction Controller - Serial number: 031144509

Change filter assembly /

Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

Date of last hose replacement:

Check rail clamp is securely attached to suction controller /

Replace suction tubing /

Replace tapered connector /

Check receiving canister for damage, replaced? OK

Radiant Warmer Serial number: YD2060 RW 14071

Is Radiant Warmer hard-wired? No

PAT test performed? YES

APGAR Timer - Serial number:

Change batteries

Check storage bins present X

Tidy any trailing hoses, using tie-wraps if necessary /

Check Operator's Manuals are in place /

Clean cabinet with isopropyl alcohol

Blender Serial number: B1551983 55604

Date of last hose replacement:

@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen

Check Alarm for no Air

Check O2/Air Balance Alarms before output change

Check Duck Bill Valves

Check for Leaks

**Cabinet Body Serial number: D004**

Check for overall signs of damage Comments - signs of wear, chipped paint  
 Check door catch - swivel catch on door ✓  
 Check door catch retaining clasp on cabinet ✓  
 Check integrity of welds on the door hinges ✓ - No cracks  
 Check hinges for damage or deformation - Slight bending, nothing significant  
 Check the restraining bars for damage or deformation - ✓  
 Check the cabinet is securely fixed to wall ✓  
 Check medirails and tighten any loose rails ✓  
 Check grommets on the hose inlets are in place and intact ✓  
 Check the bumper stops that prevent door banging during closing ✓  
 Check caution sticker is in place on the platform ✓ replaced.  
 Check bed for damage i.e. cracks, chips ✓ 12"  
 Check all the bed mounting screws are in place ✓  
 Check mattress for damage i.e. tears, split seams ✓ 12"

**Tom Thumb - Serial Number: 0000 VMEFO2**

Minimum reading less 7.85 mbar: 2.1  
 Adjustable valve 42.1 mbar +/-1: 41.6  
 Precision Valve 44.1 mbar +/-1: 43.7  
 Gauge @30cmh2o (28.4-30.4 mbar): 30.4

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

**Date of last hose replacement:**

**Low Suction Controller - Serial number: 031144520** - Cracked gauge face  
 Advised engineer.  
 Change filter assembly ✓

Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

**Date of last hose replacement: 1/10/20**

Check rail clamp is securely attached to suction controller ✓  
 Replace suction tubing ✓  
 Replace tapered connector ✓  
 Check receiving canister for damage, replaced? ✓ - ok

**Radiant Warmer Serial number: YD2064 RW**

Is Radiant Warmer hard-wired? Y - Cracked case by lamp, advised inspection by EBME.  
 PAT test performed? Y

**APGAR Timer - Serial number: None - Old style black timer**

Change batteries ✓  
 Check storage bins present - No  
 Tidy any trailing hoses, using tie-wraps if necessary ✓  
 Check Operator's Manuals are in place ✓  
 Clean cabinet with isopropyl alcohol ✓

**Blender Serial number: B1551978**

Date of last hose replacement: 1/10/20

@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen  
 Check Alarm for no Air  
 Check O2/Air Balance Alarms before output change  
 Check Duck Bill Valves  
 Check for Leaks

Returned for overhaul service. SPS67608

Service exchange blender installed

Hospital: Royal Preston

Room: 6

Date: 1/10/20

Cabinet Body Serial number: D006

Check for overall signs of damage Comments ✓  
Check door catch - swivel catch on door ✓✓  
Check door catch retaining clasp on cabinet ✓✓  
Check integrity of welds on the door hinges ✓  
Check hinges for damage or deformation ✓  
Check the restraining bars for damage or deformation ✓  
Check the cabinet is securely fixed to wall ✓  
Check medirails and tighten any loose rails ✓  
Check grommets on the hose inlets are in place and intact ✓  
Check the bumper stops that prevent door banging during closing ✓  
Check caution sticker is in place on the platform ✓  
Check bed for damage i.e. cracks, chips ✓  
Check all the bed mounting screws are in place ✓  
Check mattress for damage i.e. tears, split seams ✓

Tom Thumb - Serial Number: VMEF 009

Minimum reading less 7.85 mbar: 2.2

Adjustable valve 42.1 mbar +/-1: 41.3

Precision Valve 44.1 mbar +/-1: 43.4

Gauge @30cmh2o (28.4-30.4 mbar): 28.9

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

Date of last hose replacement:

Low Suction Controller - Serial number: 031144526

Change filter assembly ✓

Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

Date of last hose replacement: 1/10/20

Check rail clamp is securely attached to suction controller ✓

Replace suction tubing ✓

Replace tapered connector ✓

Check receiving canister for damage, replaced? ✓

Radiant Warmer Serial number: WD2042RW

Is Radiant Warmer hard-wired? ✓ Y

PAT test performed? ✓ Y

APGAR Timer - Serial number: None - Old style black timer

Change batteries ✓

Check storage bins present - None

Tidy any trailing hoses, using tie-wraps if necessary ✓

Check Operator's Manuals are in place ✓

Clean cabinet with isopropyl alcohol ✓

Blender Serial number: B1551985

Date of last hose replacement: 1/10/20

@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen

Check Alarm for no Air

Check O2/Air Balance Alarms before output change

Check Duck Bill Valves

Check for Leaks

Requires Overhaul to be returned to Vicamed.

Hospital: Royal Preston

Room: 5

Date: 1/10/20

Cabinet Body Serial number: E346

Check for overall signs of damage Comments ✓ Shuttleworths cabinet (replacement)  
Check door catch - swivel catch on door ✓  
Check door catch retaining clasp on cabinet ✓  
Check integrity of welds on the door hinges ✓  
Check hinges for damage or deformation ✓  
Check the restraining bars for damage or deformation ✓  
Check the cabinet is securely fixed to wall ✓  
Check medirails and tighten any loose rails ✓  
Check grommets on the hose inlets are in place and intact ✓  
Check the bumper stops that prevent door banging during closing - No. Gap wouldn't allow it  
Check caution sticker is in place on the platform ✓  
Check bed for damage i.e. cracks, chips ✓ 12" bed  
Check all the bed mounting screws are in place ✓  
Check mattress for damage i.e. tears, split seams 12" mattress

Tom Thumb - Serial Number: VMDI23

Minimum reading less 7.85 mbar: 2.1

Adjustable valve 42.1 mbar +/- 42.5

Precision Valve 44.1 mbar +/- 1: 44.9

Gauge @30cmh2o (28.4-30.4 mbar): 28.7

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years) - ~~Replace~~

Date of last hose replacement:

Low Suction Controller - Serial number: 03114522

Change filter assembly ✓

Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

Date of last hose replacement: 1/10/20

Check rail clamp is securely attached to suction controller ✓

Replace suction tubing ✓

Replace tapered connector ✓

Check receiving canister for damage, replaced? ✓ - ok

Radiant Warmer Serial number: YD2068RW

Is Radiant Warmer hard-wired? ✓

PAT test performed? ✓

APGAR Timer - Serial number: 00947

Change batteries ✓

Check storage bins present X - N

Tidy any trailing hoses, using tie-wraps if necessary ✓

Check Operator's Manuals are in place ✓

Clean cabinet with isopropyl alcohol ✓

Blender Serial number: B1551983

Date of last hose replacement: 1/10/20

@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen

Check Alarm for no Air

Check O2/Air Balance Alarms before output change

Check Duck Bill Valves

Check for Leaks

Service exchange Blender installed

Returned for overhaul service - SRS67608

Hospital: Royal Preston

Room: 69

Date: 1/10/20

**Cabinet Body Serial number: D005**

Check for overall signs of damage Comments ✓  
Check door catch - swivel catch on door ✓  
Check door catch retaining clasp on cabinet ✓  
Check integrity of welds on the door hinges ✓  
Check hinges for damage or deformation ✓  
Check the restraining bars for damage or deformation ✓  
Check the cabinet is securely fixed to wall ✓  
Check medirails and tighten any loose rails ✓  
Check grommets on the hose inlets are in place and intact ✓  
Check the bumper stops that prevent door banging during closing ✓  
Check caution sticker is in place on the platform ✓  
Check bed for damage i.e. cracks, chips ✓ 12"  
Check all the bed mounting screws are in place ✓  
Check mattress for damage i.e. tears, split seams ✓ 12"

**Tom Thumb - Serial Number: VMD122**

Minimum reading less 7.85 mbar: 2.6

Adjustable valve 42.1 mbar +/-1: 41.7

Precision Valve 44.1 mbar +/-1: 43.7

Gauge @30cmh2o (28.4-30.4 mbar): 30.2

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

**Date of last hose replacement:**

**Low Suction Controller - Serial number: 031163907**

Change filter assembly ✓

Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

**Date of last hose replacement: 1/10/20**

Check rail clamp is securely attached to suction controller ✓

Replace suction tubing ✓

Replace tapered connector ✓

Check receiving canister for damage, replaced? ✓ OK

**Radiant Warmer Serial number: YD2066 RW**

Is Radiant Warmer hard-wired? ✓

PAT test performed? ✓ ✓

**APGAR Timer - Serial number: -N/a old black timer type**

Change batteries ✓

Check storage bins present -No

Tidy any trailing hoses, using tie-wraps if necessary ✓

Check Operator's Manuals are in place ✓

Clean cabinet with isopropyl alcohol ✓

**Blender Serial number: B1551971**

**Date of last hose replacement: 1/10/20**

@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen

Check Alarm for no Air

Check O2/Air Balance Alarms before output change

Check Duck Bill Valves

Check for Leaks

Blender to be sent back for overhaul.

Hospital: ROYAL PRESTON

Room: 1

Date: 5/10/20

**Cabinet Body Serial number: E337**

Check for overall signs of damage Comments ✓  
Check door catch - swivel catch on door ✓  
Check door catch retaining clasp on cabinet ✓  
Check integrity of welds on the door hinges ✓  
Check hinges for damage or deformation ✓  
Check the restraining bars for damage or deformation ✓  
Check the cabinet is securely fixed to wall ✓  
Check medirails and tighten any loose rails ✓  
Check grommets on the hose inlets are in place and intact ✓  
Check the bumper stops that prevent door banging during closing ✓  
Check caution sticker is in place on the platform ✓  
Check bed for damage i.e. cracks, chips ✓  
Check all the bed mounting screws are in place ✓  
Check mattress for damage i.e. tears, split seams ✓

**Tom Thumb - Serial Number: VMDI24**

Minimum reading less 7.85 mbar: 44

Adjustable valve 42.1 mbar +/-1: 42.3

Precision Valve 44.1 mbar +/-1: 44.6

Gauge @30cmh2o (28.4-30.4 mbar): 28.7

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

**Date of last hose replacement:** 4

**Low Suction Controller - Serial number: 16431002**

Change filter assembly ✓

Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

**Date of last hose replacement:** 5/10/20

Check rail clamp is securely attached to suction controller ✓

Replace suction tubing ✓

Replace tapered connector ✓

Check receiving canister for damage, replaced? ✓ OK

**Radiant Warmer Serial number: - YD 2463 RW**

Is Radiant Warmer hard-wired? ✓

PAT test performed? ✓

**APGAR Timer - Serial number: - N/A, old black timer**

Change batteries ✓

Check storage bins present - No

Tidy any trailing hoses, using tie-wraps if necessary ✓

Check Operator's Manuals are in place ✓

Clean cabinet with isopropyl alcohol ✓

**Blender Serial number: B1551986**

**Date of last hose replacement:** 5/10/20

@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen

Check Alarm for no Air

Check O2/Air Balance Alarms before output change

Check Duck Bill Valves

Check for Leaks

Blender Requires Overhaul

Hospital: Royal Preston

Room: 10

Date: 5/10/20

**Cabinet Body Serial number: D002**

- Check for overall signs of damage Comments ✓
- Check door catch - swivel catch on door ✓
- Check door catch retaining clasp on cabinet ✓
- Check integrity of welds on the door hinges ✓
- Check hinges for damage or deformation ✓
- Check the restraining bars for damage or deformation ✓
- Check the cabinet is securely fixed to wall ✓
- Check medirails and tighten any loose rails ✓
- Check grommets on the hose inlets are in place and intact ✓
- Check the bumper stops that prevent door banging during closing ✓
- Check caution sticker is in place on the platform ✓
- Check bed for damage i.e. cracks, chips ✓
- Check all the bed mounting screws are in place ✓
- Check mattress for damage i.e. tears, split seams ✓

**Tom Thumb - Serial Number: VMEF05**

Minimum reading less 7.85 mbar: 1.7  
Adjustable valve 42.1 mbar +/-1: 42.0  
Precision Valve 44.1 mbar +/-1: 43.3  
Gauge @30cmh2o (28.4-30.4 mbar): 29.5

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

**Date of last hose replacement:**

**Low Suction Controller - Serial number: 031144530**

- Change filter assembly ✓
- Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓
- Date of last hose replacement:** 5/10/20
- Check rail clamp is securely attached to suction controller ✓
- Replace suction tubing ✓
- Replace tapered connector ✓
- Check receiving canister for damage, replaced? ✓

**Radiant Warmer Serial number: YD2061RW**

Is Radiant Warmer hard-wired? ✓  
PAT test performed? ✓

**APGAR Timer - Serial number: - N/A old black style time**

- Change batteries ✓
- Check storage bins present ✗ - No.
- Tidy any trailing hoses, using tie-wraps if necessary ✓
- Check Operator's Manuals are in place ✓
- Clean cabinet with isopropyl alcohol ✓

**Blender Serial number: B1551982**

**Date of last hose replacement:** 5/10/20

@20.9:      @30:      @60:      @90:      @100:      (+/-3)

- Check Alarm for no Oxygen
- Check Alarm for no Air
- Check O2/Air Balance Alarms before output change
- Check Duck Bill Valves
- Check for Leaks

Requires overhaul

Hospital: Royal Preston

Room: 11

Date: 5/10/

**Cabinet Body Serial number: D010**

- Check for overall signs of damage Comments ✓
- Check door catch - swivel catch on door ✓
- Check door catch retaining clasp on cabinet ✓
- Check integrity of welds on the door hinges ✓
- Check hinges for damage or deformation ✓
- Check the restraining bars for damage or deformation ✓
- Check the cabinet is securely fixed to wall ✓
- Check medirails and tighten any loose rails ✓
- Check grommets on the hose inlets are in place and intact ✓
- Check the bumper stops that prevent door banging during closing ✓
- Check caution sticker is in place on the platform ✓
- Check bed for damage i.e. cracks, chips ✓
- Check all the bed mounting screws are in place ✓
- Check mattress for damage i.e. tears, split seams ✓

**Tom Thumb - Serial Number: VMDI21**

Minimum reading less 7.85 mbar: 1.3  
Adjustable valve 42.1 mbar +/-1: 41.5  
Precision Valve 44.1 mbar +/-1: 43.6  
Gauge @30cmh2o (28.4-30.4 mbar): 28.4

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

**Date of last hose replacement:**

**Low Suction Controller - Serial number: 031144510**

- Change filter assembly ✓
- Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓

**Date of last hose replacement: 5/10/20**

- Check rail clamp is securely attached to suction controller ✓
- Replace suction tubing ✓
- Replace tapered connector ✓
- Check receiving canister for damage, replaced? ✓

**Radiant Warmer Serial number: YD2065RW**

- Is Radiant Warmer hard-wired? ✓
- PAT test performed? ✓

**APGAR Timer - Serial number: 0091644510**

- Change batteries ✓
- Check storage bins present ✓ N
- Tidy any trailing hoses, using tie-wraps if necessary ✓
- Check Operator's Manuals are in place ✓
- Clean cabinet with isopropyl alcohol ✓

**Blender Serial number: B1551984**

**Date of last hose replacement: 5/10/20**

@20.9: @30: @60: @90: @100: (+/-3)

- Check Alarm for no Oxygen
- Check Alarm for no Air
- Check O2/Air Balance Alarms before output change
- Check Duck Bill Valves
- Check for Leaks

Requires overhaul

Hospital: Royal Preston

Room: 12

Date: 5/10/20

**Cabinet Body Serial number: D100**

Check for overall signs of damage Comments ✓  
Check door catch - swivel catch on door ✓  
Check door catch retaining clasp on cabinet ✓  
Check integrity of welds on the door hinges ✓  
Check hinges for damage or deformation ✓  
Check the restraining bars for damage or deformation ✓  
Check the cabinet is securely fixed to wall ✓  
Check medirails and tighten any loose rails ✓  
Check grommets on the hose inlets are in place and intact ✓  
Check the bumper stops that prevent door banging during closing ✓  
Check caution sticker is in place on the platform ✓  
Check bed for damage i.e. cracks, chips ✓  
Check all the bed mounting screws are in place ✓  
Check mattress for damage i.e. tears, split seams ✓

**Tom Thumb - Serial Number: VMEFO4**

Minimum reading less 7.85 mbar: 3.1  
Adjustable valve 42.1 mbar +/-1: 42.3  
Precision Valve 44.1 mbar +/-1: 43.3  
Gauge @30cmh2o (28.4-30.4 mbar): 29.9

Check oxygen hose, if present, for wear, and replace if necessary (at least every 4 years)

**Date of last hose replacement:**

**Low Suction Controller - Serial number: 031144525**

Change filter assembly ✓  
Check vacuum hose for wear, and replace if necessary (at least every 4 years) ✓  
**Date of last hose replacement: 5/10/20**  
Check rail clamp is securely attached to suction controller ✓  
Replace suction tubing ✓  
Replace tapered connector ✓  
Check receiving canister for damage, replaced? ✓ - No, ok.

**Radiant Warmer Serial number: ZW2198ZW**

Is Radiant Warmer hard-wired? ✓  
PAT test performed? ✓

**APGAR Timer - Serial number: -N/A - old style timer**

Change batteries ✓  
Check storage bins present ✗ No. Not required  
Tidy any trailing hoses, using tie-wraps if necessary ✓  
Check Operator's Manuals are in place ✓  
Clean cabinet with isopropyl alcohol ✓

**Blender Serial number: B1551971**

**Date of last hose replacement: 05/10/20**  
@20.9: @30: @60: @90: @100: (+/-3)

Check Alarm for no Oxygen  
Check Alarm for no Air  
Check O2/Air Balance Alarms before output change  
Check Duck Bill Valves  
Check for Leaks

Requires over-haul.