



Enter CID Number

Link Company ID

SRS67874

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care
Add Items to Supplier Returns Box

Add

- ☐ Return for Credit / Return to Stock Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

Add Notes

Uploaded Documents

02 Aug 2021 SRS67874 SRN34001 Catherine Spence

Service Repair Sheet 67874		Notes
Company / Hospital	JFD	22/Jun/2021 Steve Nixon
Contact Name	Duncan Clark	22/Jun/2021 Steve Nixon 22/Jun/2021 Steve Nixon
Department		Unstable high output. Test to see if could be caused by a bubble. Discuss with SN.
Position		13/Jul/2021 Robert Connor
Company Phone		1 x JFD sensor s/n 102258, with truncated wires
Direct Phone		16/Jul/2021 Catherine Spence requested on box 803
Opera Account		22/Jul/2021 Catherine Spence returned back to supplier
Email		02/Aug/2021 Catherine Spence Credit received from supplier
Order Number		02/Aug/2021 Catherine Spence Failed as signal out of tolerance
ViaMed ORD Number		02/Aug/2021 Catherine Spence Send replacement sensor on next order
Date Received Into building	13 Jul 2021	13/Sep/2021 Catherine Spence waiting on next order/stock to be replaced on CST131968
Type	Warranty	20/Sep/2021 Catherine Spence replacing on next order
Issues?	229363 230926 230927 236532	LINKED ISSUE NOTES: 229363: AutoGenerated Issue SRS67874 Appears to be Complete 22 Jul 2021 Catherine Spence noted returned back to supplier 230926: AutoGenerated Issue SRS67874 Appears to be Complete 04 Aug 2021 Catherine Spence noted 230927: Added by Catherine Spence sent to Sarah Walton Next time JFD order sensors, please can you edit the order to cover a warranty replacement sensor from SRS67874 To replace S/N: 102258 SRS67874 SRN34001 for warranty replacement 06 Aug 2021 Sarah Walton Done 11 Aug 2021 Catherine Spence

[236532:](#)

AutoGenerated Issue SRS67874 Appears to be Complete

24 Sep 2021 Catherine Spence
completed**Items for Repair**

...

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)	
SRN34001	Oxygen Sensor VST	8010050	1692342	102258	Oxygen Sensor - JFD	Yes	No	Replaced	High Output	00:00	   RST131968-2

Currently Viewing ITEM SRN34001 Oxygen Sensor VST 8010050 102258 Oxygen Sensor - JFD[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Replaced under warranty with S/N:103011	16/Jul/2021 Michael Green The JFD Oxygen sensor has been tested. The output in air was 62.0mV. The output would vary if the sensor was tipped. The sensor will be returned to the supplier for investigation. 02/Aug/2021 Catherine Spence failed as signal out of tolerance 22/Sep/2021 Catherine Spence Replaced under warranty with S/N:103011	Replaced under warranty with S/N:103011

-