



Odběratel: Divesoft s.r.o. K Haltýři 14 180 00 Praha 8 Provozovna: Roudnice nad Labem Hálkova 2495 413 01 Roudnice nad Labem IČ: 26722101 DIČ: CZ26722101 Telefon: +420416857057 E-mail: cz.info@divesoft.com www.divesoft.com		Tel.:
Objednávka č.: 23OB0251 Forma úhrady: Příkazem Datum objednávky: 17.04.2023		Dodavatel: Vandagraph Sensor Technologies 15 Station Road, Cross Hills, Keighley West Yorkshire, United Kingdom
		IČ:

Označení dodávky	Množství	J.cena	Sleva	Celkem
Complain to the order : 22OB0714				
3092:8010020 Oxygen Sensor - type 22D	4 pcs	29,35		117,40
CELKEM K ÚHRADĚ	Částky jsou uvedeny v GBP			117,40

Returns number:**Oxygen Sensor type 22D :** D109803, D110940, D111154, D111154,

The issue with some sensor is, that sensor haven't connection when the sensor is properly connected to molex connector. When you release the lock of the connector and move with connector to the half way, then the sensor have connection and work properly. All the sensort with this issue are tested also with another molex connectors, but result is still same.

Please confirm the receipt of the complaint and specify the date of the complaint.

Vystavil: Katarína Řepová
office.cz@divesoft.com

Převzal:	Razítko:
Ekonomický a informační systém POHODA	