

VM3COP61.14 2520020 Patient lead QA procedure

Equipment list:

Multi-meter
Multi-meter test adapter

- 1) Connect the black and red leads to the test adapter.
- 2) In turn, connect the red and black crocodile connectors to the test contact on the adapter.
- 3) Set the multi-meter to a continuity test.
- 4) Ensure each lead has continuity and that the connector colours correspond.
- 5) Enter the QA information into the Intrastats system.

