

MHRA report number: **2012/001/018/401/002**

Product: **Flowsensor A**

Part number: **4310001**

Customer complaint from:

Adrian Morgan
Nottingham University Hospitals Trust - City Campus
Clinical Engineering

adrian.morgan@nuh.nhs.uk
Tel. 01159 691169 ext 55787

Email received from Mr Morgan 18/01/12 at 16:37

Information Request to Viamed Limited at the <http://www.viamed.co.uk/eng/>
WebSite

Adrian Morgan
Nottingham University Hospitals Trust - City Campus
Clinical Engineering
adrian.morgan@nuh.nhs.uk
United Kingdom EU
Type: Technical

We have experienced an incident involving one of your Flowsensor A flow sensors fitted to a Draeger Evita XL ventilator. The sensor caught fire shortly after being fitted (new sensor). The MHRA have been informed as have Draeger. We are currently awaiting instruction from MHRA.

Adrian Morgan

Tel 01159 691169 ext 55787

Request further Information on