



steve nixon <steve.nixon.viamed@googlemail.com>

R-24MED quality issues

1 message

Steve Nixon <steve.nixon@viamed.co.uk>

22 April 2013 11:00

To: Vasu Narasimhan <VNarasimhan@teledyne.com>

Cc: kunal <KKothari@teledyne.com>

Dear Vasu

There appears to be some quality issues regarding R-24MED sensors:

- a) Molex connector off centre and Molex pins bent to one side, (2 pictures attached)
- b) Input thread damaged, (1 picture attached)
- c) Scuffing of plastic casing.

Steve

3 attachments



R24 thread.jpg

55K



R24 bent pins 2.jpg
38K



R24 bent pins 1.jpg
44K