

Meeting Date: 27/05/14 : Meeting Called by: _____ Meeting Lasted _____ Minutes

Ad-Hoc Meeting - Ad-Hoc Meeting
#50406 Ad-Hoc Meeting

☒ VST

☐ VANDAGRAPH

☐ VIAMED

☐ Catherine Spence	☐ Catrin Hird	☒ Derek Lamb	☐ Emily Hanson	☐ Helen Lamb
☐ Jean Lamb	☐ John Lamb	☐ Jonathan Connor	☐ Keith Taylor	☐ Linda Shearing
☐ Lisa Leggoe	☐ Michael Green	☐ Michael Lamb	☐ Philip Crossley	☐ Robert Connor
☐ Ruth Hardaker	☐ Ryan Swaine	☐ Sophie Lines	☐ Steve Hardaker	☒ Steve Nixon
☐ Xhibition				

B136 Lamer Diveright under misinterpretation
Should be back on board

more Dialogue between Costumes

1st Seminar 2 sensors failures and unit. Incident VR TECH
was using Teledyne Sensors 33 months old. He just Blackout
APD Replace by Default Replace Sensors on Service
VR DID NOT change by Default on Service.

US Nancy guys.

Marlin New units
Paul Raydler
Dave Thompson -

Bruce Shearwater!

innerSpace Hi

Hardware

in sensor slow Response Low power

MAXtec
Bruce

Innerspace, Whalley
Semy Airport

Teledyne

Tam/Karel late
Vase man died